

ANNUAL SURVEYS.

No. 14203 Survey held at London Date, first Survey 29 Oct. Last Survey 31st Oct. 1877
 No. in on the S.S. "City of Oxford" Master J. Gordon
 Reg. Book. 857 Tonnage 1497 Built at Glasgow When built 1870 - 10 mo.
 By whom built Barclay Owners G. Smith & Sons
 Port belonging to Glasgow Destined Voyage
 If Surveyed Afloat or in Dry Dock Millwall & Dry Dock - Afloat

Last Survey, No. 14203 Port of London

Classed

Years assigned.

Character in Register Book.

100 A.I.

3.75

Present Condition of the

Decks good

Waterways "

Comings "

Upper Deck Beams & Fastenings "

Deck Beams & Fastenings "

Planksheers "

Strakes "

Sides "

Bottom (Bottom) and Counter "

Engine Room Skylights good

General Observations, Opinion as to Class, &c. Surveyed with ballast in hold.

Treenails ✓

Breasthooks and Stemson not seen.

Transoms, Pointers, and Crutches surveyed

Timbers of the Frame at the Openings with

Ditto ditto at other places Ballast

Keelsons in hold

Clamps and Shelves good

Ceiling "

Rudder (Rebushed)

Copper or Y.M. ✓ When put on ✓

Caulking of good

Bottom, Deck, & Waterways good

Windlass and Capstan good

Pumps 6 no.

Boats 6 no.

Masts, Yards, &c. from deck

Condition, how ascertained good

Sails 3 B, 15, 2 K.

Anchors, No. of 3 B, 15, 2 K.

Cables good

Hawsers and Warps "

Standing and Running Rigging "

Coal Bunker, Openings, Lids, &c. good Scuppers good Cargo and Main Hatchways good Hatches good

Bottom cleaned and repainted -

Rudder unshipped and pintles rebushed -

This vessel appears to be in good and efficient condition and eligible to remain as at present classed.

Committee's Minute 9th November, 1877.

Character assigned 100 A.I.

J. P. M.

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required) Paid 18

No. 17847 Survey held at London Date, first Survey 25 Oct. Last Survey 29 Oct. 1877
 No. in on the S.S. "Avena" Master Hellberg
 Reg. Book. 525 Tonnage 459 Built at Sunderland When built 1873 - 9 mo.
 By whom built Davison Owners W. Thorburn
 Port belonging to Uddervalla Destined Voyage
 If Surveyed Afloat or in Dry Dock Millwall & Dry Dock

Last Survey, No. *17847 Port of London

Classed

Years assigned.

Character in Register Book.

90 A.I.

2.77

Present Condition of the

Decks good

Waterways "

Comings "

Upper Deck Beams & Fastenings "

Lower Deck Beams & Fastenings "

Planksheers "

Strakes "

Sides "

Bottom (Bottom) and Counter "

Engine Room Skylights good

General Observations, Opinion as to Class, &c. Bottom cleaned and repainted.

Treenails ✓

Breasthooks and Stemson not seen

Transoms, Pointers, and Crutches surveyed

Timbers of the Frame at the Openings with

Ditto ditto at other places ballast

Keelsons in hold

Clamps and Shelves good

Ceiling when seen

Rudder good

Copper or Y.M. ✓ When put on ✓

Caulking of good

Bottom, Deck, & Waterways good

Windlass and Capstan good

Pumps 3 no.

Boats 3 no.

Masts, Yards, &c. from deck

Condition, how ascertained good

Sails 3 B, 15 & 2 K

Anchors, No. of 3 B, 15 & 2 K

Cables good

Hawsers and Warps "

Standing and Running Rigging "

Coal Bunkers, Openings, Lids, &c. good Scuppers good Cargo and Main Hatchways good Hatches good

Bottom cleaned and repainted.

This vessel appears to be in good and efficient condition, and eligible to remain as classed.

Committee's Minute 9th November, 1877.

Character assigned 90 A.I.

J. P. M.

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required) Paid 18