

ANNUAL SURVEYS.

19703
Survey held at London Date, first Survey 5/11/77 Last Survey 9 Nov 1877
on the S. "Ellen Stuart" Master Reid
Tonnage 572, 1649, 112 Built at Liverpool When built 1854
By whom built - Owners Stuart & Douglas
Port belonging to Liverpool Destined Voyage Calcutta
If Surveyed Afloat or in Dry Dock In dry dock & afloat

Last Survey, No. 17768 Port of Liverpool Classed 90 A. 1. 1877
S. S. London 1874.

Present Condition of the
Planks Good Treennails Rivets Good
Waterways --- Breasthooks and Stemson ---
Rings --- Transoms, ~~Pointers~~, and Crutches ---
Upper Deck Beams & Fastenings --- ~~Timbers~~ of the Frame at the Openings ---
Lower Deck Beams & Fastenings --- Ditto ditto at other places not seen
Planksheers --- Keelsons Good
Steeprakes --- Clamps and Shelves ---
Oppsides --- Ceiling ---
Sides --- Rudder ---
Sides (Bottom) and Counter --- Copper or P.M. Paint When put on now
Caulking of Bottom, Deck, & Waterways Good
Engine Room Skylights ✓ Coal Bunker, Openings, Lids, &c. ✓ Scuppers --- Cargo and Main Hatchways Good Hatches ---
General Observations, Opinion as to Class, &c. Bottom cleaned and painted.

Surveyed with coal in main hold. Cement and brick ballast dug out from between the floors in fore & after holds.
This ship app^r to be in good condition and is eligible in my opinion to remain classed 90 A. 1.

Committee's Minute 4th December, 1877. J. W. Scullard
Character assigned 90 A. 1 Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required) --- Paid 18

Survey held at London Date, first Survey 16 Nov 1877 Last Survey 16 Nov 1877
on the S. "Lord Lyndhurst" Master Robertson
Tonnage 1187 Built at Liverpool When built 1861 - 11 Nov
By whom built Vernon Owners Farnworth & Jardine
Port belonging to Liverpool Destined Voyage ---
If Surveyed Afloat or in Dry Dock Poultion - Vic. dock

Last Survey, No. 17276 Port of Liverpool Classed 90 A. 1. 1876
S. S. Liverpool 1874.

Present Condition of the
Planks Good Treennails Rivets Good
Waterways --- Breasthooks and Stemson ---
Rings --- Transoms, ~~Pointers~~, and Crutches ---
Upper Deck Beams & Fastenings --- ~~Timbers~~ of the Frame at the Openings ---
Lower Deck Beams & Fastenings --- Ditto ditto at other places not seen
Planksheers --- Keelsons ---
Steeprakes --- Clamps and Shelves ---
Oppsides --- Ceiling ---
Sides --- Rudder ---
Sides (Bottom) and Counter --- Copper or P.M. Paint When put on now
Caulking of Bottom, Deck, & Waterways Good
Engine Room Skylights --- Coal Bunkers, Openings, Lids, &c. --- Scuppers --- Cargo and Main Hatchways Good Hatches ---
General Observations, Opinion as to Class, &c. Bottom cleaned and painted, rudder lifted and brushed. Forecastle deck partially renewed and the whole caulked. Fore topmast renewed.

Surveyed in ballast. Ship app^r to be in good condition and is eligible in my opinion to remain classed 90 A. 1.

Committee's Minute 4th December, 1877. J. W. Scullard
Character assigned 90 A. 1 Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required) --- Paid 18