

ANNUAL SURVEYS.

No. 19722 Survey held at London Date, first Survey 30/10 Last Survey 5-11-77 1877
 No. in on the Reg. Book. 625 Tonnage 728, 1812, 1600 Built at Sunder Master Hean
 By whom built Slipken Owners David Bruce
 Port belonging to Sunder Destined Voyage -
 If Surveyed Afloat or in Dry Dock Blackwall paint dock.

1st Survey, No. 17145 Port of Iron
 Condition of the Deck Good Treenails Rivets Good
 Waterways - Breasthooks and Stemson -
 Coming - Transoms, ~~Pointers~~, and Crutches -
 Upper Deck Beams & Fastenings - ~~Timbers~~ of the Frame at the Openings -
 Lower Deck Beams & Fastenings - ~~Ditto~~ ditto at other places -
 Planksheers - Keelsons -
 Sheerstrakes - Clamps and Shells -
 Topsides - Ceiling -
 Wales - Rudder -
 Plank (bottom) and Counter - Copper or Y.M. Paint When put on now
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights ✓ Coal Bunker, Openings, Lids, &c. ✓ Scuppers - Cargo and Main Hatchways Good Hatches -
 General Observations, Opinion as to Class, &c.

Surveyed in ballast. Bottom sighted, scraped and painted. This ship is in good condition and eligible in my opinion to remain classed 100 A.1.

Committee's Minute 7th December, 1877.
 Character assigned 100 A.1

J. W. Scullard
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) - Paid - 18 -

No. 1014 Survey held at London Date, first Survey 1/11 Last Survey 5th Dec 1877
 No. in on the Reg. Book. 1014 Tonnage 949, 949, 919 Built at Belfast Master Coulter
 By whom built Harland Owners J. Barry & Co
 Port belonging to Belfast Destined Voyage -
 If Surveyed Afloat or in Dry Dock Greens' dock

Survey, No. 17819 Port of Iron
 Condition of the Deck Good Treenails Rivets Good
 & Fastenings - Breasthooks and Stemson -
 & Fastenings - Transoms, ~~Pointers~~, and Crutches -
 & Fastenings - ~~Timbers~~ of the Frame at the Openings -
 & Fastenings - ~~Ditto~~ ditto at other places -
 Keelsons -
 Clamps and Shells -
 Ceiling -
 Rudder -
 Copper or Y.M. Paint When put on now
 Caulking of Bottom, Deck, & Waterways Good
 Coal Bunkers, Openings, Lids, &c. - Scuppers - Cargo and Main Hatchways Good Hatches -
 Opinion as to Class, &c.

Surveyed in ballast. Bottom sighted, cleaned and scrubbed. Rudder lifted and bushed. Ship is in good condition and eligible in my opinion to remain classed *A.1.

Committee's Minute 7th December, 1877.
 Character assigned *A.1

J. W. Scullard
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) - Paid - 18 -