

19736

ANNUAL SURVEYS.

36733

Recd 29. 11. 77

No. in Reg. Book. 1195 on the SS Mirfield Survey held at London Date, first Survey Nov 22 Last Survey 1877
Master W Atkinson
Tonnage 867 Built at Greenock When built 1871 11 M
By whom built Scott Owners J B Cranshall
Port belonging to London Destined Voyage
If Surveyed Afloat or in Dry Dock Dry Dock

Last Survey, No. 19297 Port of London
Classed 100 A 877
Years assigned. SS Lon M-76
Character in Register Book.
Present Condition of the
Decks Good Treennails Rivets Good
Waterways " Breasthooks and Stemson "
Comings " Transoms, Pointers, and Crutches "
Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
Lower Deck Beams & Fastenings " Ditto ditto at other places "
Planksheers " Keelsons "
Sheerstrakes " Clamps and Shelves "
Topsides " Ceiling "
Wales " Rudder "
Plank (Bottom) and Counter " Copper or Y.M. Coated When put on now
Caulking of Bottom, Deck, & Waterways Good
Engine Room Skylights Good Coal Bunker, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good
General Observations, Opinion as to Class, &c. Bottom Scraped & Coated.

She is now in good condition and entitled to remain as classed

Senhouse Martindale

Committee's Minute 4th December, 1877.
Character assigned 100
Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required) Paid 18

No. in Reg. Book. 7 on the SS H P Stephenson Survey held at London Date, first Survey Nov 20th Last Survey 1877
Master
Tonnage 624 Built at Newcastle When built 1871 11 M
By whom built 962 Richardsen Owners Gen Jan Senhouse & Co
Port belonging to London Destined Voyage
If Surveyed Afloat or in Dry Dock Dry Dock

Last Survey, No. 18881 Port of London
Classed 90 A 877
Years assigned. SS Lon M-76
Character in Register Book.
Present Condition of the
Decks Good Treennails Rivets Good
Waterways " Breasthooks and Stemson "
Comings " Transoms, Pointers, and Crutches "
Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
Lower Deck Beams & Fastenings " Ditto ditto at other places "
Planksheers " Keelsons "
Sheerstrakes " Clamps and Shelves "
Topsides " Ceiling "
Wales " Rudder "
Plank (Bottom) and Counter " Copper or Y.M. Coated When put on now
Caulking of Bottom, Deck, & Waterways Good
Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good
General Observations, Opinion as to Class, &c. Bottom Scraped & Coated.

She is now in good condition and entitled to remain as classed

Senhouse Martindale

Committee's Minute 4th December, 1877.
Character assigned 90
Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required) Paid 18

120N 75-0058