

ANNUAL SURVEYS.

19743
No. in Reg. Book. **8** on the **S Nagpore** Survey held at **London** Date, first Survey _____ Last Survey **Nov 22 1877**
Tonnage **1209** Built at **Glasgow** Master **J Morrison**
By whom built **Burclay** Owners **W Rorne**
Port belonging to **Liverpool** Destined Voyage _____
If Surveyed Afloat or in Dry Dock **by St Ballast in**

Last Survey, No. **17898** Port of **Iron**
Present Condition of the
Decks **Good** Treenails **Rivet** **Good**
Waterways **"** Breasthooks and Stemson **"**
Comings **"** Transoms, Pointers, and Crutches **"**
Upper Deck Beams & Fastenings **"** Timbers of the Frame at the Openings **"**
Lower Deck Beams & Fastenings **"** Ditto ditto at other places **"**
Planksheers **"** Keelsons **"**
Sheerstrakes **"** Clamps and Shelves **"**
Topsides **"** Ceiling **"**
Wales **"** Rudder **"**
Plank (Bottom) and Counter **"** Copper or Y.M. **Coated** When put on **Now**
Engine Room Skylights **"** Caulking of Bottom, Deck, & Waterways **Good**
Coal Bunker, Openings, Lids, &c. **"** Scuppers **Good** Cargo and Main Hatchways **Good** Hatches **Good**
General Observations, Opinion as to Class, &c. **Bottom scraped & coated**
She is now in good condition and entitled to remain as classed

Classed ***A** 1276
Years assigned. **SS Iron 1875-76**
Character in Register Book.

Committee's Minute **4th December, 1877.**
Character assigned **A 1**
Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required) _____ Paid _____ 18 _____

No. **227** on the **S Western Monarch** Survey held at **London** Date, first Survey _____ Last Survey **Nov 21 1877**
Tonnage **1315** Built at **Barrow** Master _____
By whom built **Barrow S Co** Owners **Royal Exchange Ship Co.**
Port belonging to **London** Destined Voyage _____
If Surveyed Afloat or in Dry Dock **by St Ballast in**

Last Survey, No. **17554** Port of **Iron**
Present Condition of the
Decks **Good** Treenails **Rivet** **Good**
Waterways **"** Breasthooks and Stemson **"**
Comings **"** Transoms, Pointers, and Crutches **"**
Upper Deck Beams & Fastenings **"** Timbers of the Frame at the Openings **"**
Lower Deck Beams & Fastenings **"** Ditto ditto at other places **"**
Planksheers **"** Keelsons **"**
Sheerstrakes **"** Clamps and Shelves **"**
Topsides **"** Ceiling **"**
Wales **"** Rudder **"**
Plank (Bottom) and Counter **"** Copper or Y.M. **Coated** When put on **Now**
Engine Room Skylights **"** Caulking of Bottom, Deck, & Waterways **Good**
Coal Bunkers, Openings, Lids, &c. **"** Scuppers **Good** Cargo and Main Hatchways **Good** Hatches **Good**
General Observations, Opinion as to Class, &c. **Bottom scraped & coated**
She is now in good condition and entitled to remain as classed

Classed **100 A 1276**
Years assigned. **SS Iron 1875-76**
Character in Register Book.

Committee's Minute **4th December, 1877.**
Character assigned **100 A 1**
Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required) _____ Paid _____ 18 _____