

# ANNUAL SURVEYS.

19743  
No. in Reg. Book. **8** on the **S Nagpore** Survey held at **London** Date, first Survey **1877** Last Survey **Nov 22 1877**  
Tonnage **1209** Built at **Glasgow** When built **1863** 9 mo.  
By whom built **Burclay** Owners **W Rorne**  
Port belonging to **Liverpool** Destined Voyage  
If Surveyed Afloat or in Dry Dock **by St Ballast in**

Last Survey, No. **17898** Port of **Iron** Classed **\*A/ 1276**  
Present Condition of the  
Decks **Good** Treenails **Rivet** **Good**  
Waterways **"** Breasthooks and Stemson **"**  
Comings **"** Transoms, Pointers, and Crutches **"**  
Upper Deck Beams & Fastenings **"** Timbers of the Frame at the Openings **"**  
Lower Deck Beams & Fastenings **"** Ditto ditto at other places **"**  
Planksheers **"** Keelsons **"**  
Sheerstrakes **"** Clamps and Shelves **"**  
Topsides **"** Ceiling **"**  
Wales **"** Rudder **"**  
Plank (Bottom) and Counter **"** Copper or Y.M. **Coated** When put on **Now**  
Engine Room Skylights **"** Coal Bunker, Openings, Lids, &c. **"** Scuppers **Good** Cargo and Main Hatchways **Good** Hatches **Good**  
General Observations, Opinion as to Class, &c. **Bottom scraped & coated**

*She is now in good condition and entitled to remain as classed*

Committee's Minute **4th December, 1877.**  
Character assigned **\*A 1** Surveyor to Lloyd's Register of British and Foreign Shipping.  
Certificate (if required) **Paid 18**

No. **227** on the **S Western Monarch** Survey held at **London** Date, first Survey **1877** Last Survey **Nov 21 1877**  
Tonnage **1315** Built at **Barrow** When built **1875** 8M  
By whom built **Barrow S Co** Owners **Royal Exchange Ship Co.**  
Port belonging to **London** Destined Voyage  
If Surveyed Afloat or in Dry Dock **by St Ballast in**

Last Survey, No. **17554** Port of **Iron** Classed **100A/ 1276**  
Present Condition of the  
Decks **Good** Treenails **Rivet** **Good**  
Waterways **"** Breasthooks and Stemson **"**  
Comings **"** Transoms, Pointers, and Crutches **"**  
Upper Deck Beams & Fastenings **"** Timbers of the Frame at the Openings **"**  
Lower Deck Beams & Fastenings **"** Ditto ditto at other places **"**  
Planksheers **"** Keelsons **"**  
Sheerstrakes **"** Clamps and Shelves **"**  
Topsides **"** Ceiling **"**  
Wales **"** Rudder **"**  
Plank (Bottom) and Counter **"** Copper or Y.M. **Coated** When put on **Now**  
Engine Room Skylights **"** Coal Bunkers, Openings, Lids, &c. **"** Scuppers **Good** Cargo and Main Hatchways **Good** Hatches **Good**  
General Observations, Opinion as to Class, &c. **Bottom scraped & coated**

*She is now in good condition and entitled to remain as classed*

Committee's Minute **4th December, 1877.**  
Character assigned **100** Surveyor to Lloyd's Register of British and Foreign Shipping.  
Certificate (if required) **Paid 18**