

19759 + 19765

Report of Survey for Repairs of Engines and Boilers.

No. 25859

No. in Reg. Book. Survey held at Liverpool Date, first Survey 11th May Last Survey 20th June 1877
579 on the Iron S.S. "Tyne Queen" Master Casson
Tons 626 Owners Grim & Slater Port belonging to Liverpool Classed Years assigned. Character in Register Book. A1.

Diameter of Cylinder 2 of 19 $\frac{1}{2}$ " 2 of 43" Engines made at Newcastle, Compound led by Taylor in 1870
of Stroke 33" Steam 75 lbs. By whom made Taylor & Bay Birkh^d
Horse Power 140

Particulars of Repairs and Examination

2 New Boilers fitted. New spring safety valves cocks chests and connections fitted. New donkey boiler fitted. Cylinder covers, valves, pumps, main bearings valve gearing &c opened out cleaned & repaired. Propeller shaft removed & relined. New bottom blow off cocks fitted.

The Amount of Fee ... £ : : received by me, }
Certificate (if required) ... £ : : 187 }

(Travelling Expenses, if any, £

Committee's Minute Liverpool Dec^r 7th 1877.

A1 Lloyd's & Co in Red June/77.

W. H. H. H.

J. G. Wingham
Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.