

ANNUAL SURVEYS.

No. 24/10/77

No. 13796 Survey held at Newcastle Date, first Survey 4th Last Survey 7th Dec 1877
 No. in on the Iron S.S. "Aberfoyle" Master A. Cook
 Reg. Book. 15 903 1157 Built at Sunderland When built 1877-4 mo
 Tonnage 738 By whom built Thompson Owners Adam & Co
 Port belonging to Aberdeen Destined Voyage Marseilles
 Surveyed Afloat or in Dry Dock Wallsend Slip

Last Survey, No. 18554 Port of Iron Classed 100 A.1. Years assigned. 6,77 Character in Register Book.

Present Condition of the	Decks	Tronails	Rivets	Good	Windlass and Capstan	Good
Waterways	<u>d</u>	Breasthooks and Stemson	<u>d</u>	<u>d</u>	Pumps	<u>d</u>
Comings	<u>d</u>	Transoms, Pointers, and Crutches	<u>d</u>	<u>d</u>	Boats	<u>d</u>
Upper Deck Beams & Fastenings	<u>d</u>	Timbers of the Frame at the Openings	<u>d</u>	<u>d</u>	Masts, Yards, &c.	<u>d</u>
Lower Deck Beams & Fastenings	<u>d</u>	Ditto ditto at other places	<u>d</u>	<u>d</u>	Condition, how ascertained	<u>by examination</u>
Planksheers	<u>d</u>	Keelsons	<u>d</u>	<u>d</u>	Sails	<u>3</u>
Sheerstrakes	<u>d</u>	Clamps and Shelves	<u>d</u>	<u>d</u>	Anchors, No. of	<u>3</u>
Topsides	<u>d</u>	Ceiling	<u>d</u>	<u>d</u>	Cables	<u>3</u>
Wales	<u>d</u>	Rudder	<u>d</u>	<u>d</u>	Hawsers and Warps	<u>3</u>
Plank (Bottom) and Counter	<u>d</u>	Copper or V.M. paint	<u>When put on now</u>	<u>d</u>	Standing and Running Rigging	<u>Good</u>
Engine Room Skylights	<u>Good</u>	Caulking of Bottom, Deck, & Waterways	<u>Good</u>	<u>Good</u>	Cargo and Main Hatchways	<u>Good</u>
Coal Bunkers, Openings, Lids, &c.	<u>Good</u>	Scuppers	<u>Good</u>	<u>Good</u>	Hatches	<u>Good</u>

General Observations, Opinion as to Class, &c.
a few rivets in the bottom renewed, the after tank filled with water and tested, Bottom sighted, cleaned and painted. She is now in good and efficient condition, and eligible to remain as classed.

Committee's Minute 24th Dec 1877 Special £1.1.0
 Character assigned 100 A.1 T. Moverly
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) TRW Paid 18

No. 13796 Survey held at Newcastle Date, first Survey 10th Last Survey 11th Dec 1877
 No. in on the S.S. "Wimbledon" Master
 Reg. Book. 430 1474 1474 Built at Stockton When built 1872-12 mo
 Tonnage 957 By whom built Richardson Owners Dixon & Harris
 Port belonging to London Destined Voyage
 Surveyed Afloat or in Dry Dock Wallsend Slip

Last Survey, No. 18622 Port of Iron Classed 100 A.1. Years assigned. 5,77 Character in Register Book.

Present Condition of the	Decks	Tronails	Rivets	Good	Windlass and Capstan	Good
Waterways	<u>d</u>	Breasthooks and Stemson	<u>d</u>	<u>d</u>	Pumps	<u>d</u>
Comings	<u>d</u>	Transoms, Pointers, and Crutches	<u>d</u>	<u>d</u>	Boats	<u>d</u>
Upper Deck Beams & Fastenings	<u>d</u>	Timbers of the Frame at the Openings	<u>d</u>	<u>d</u>	Masts, Yards, &c.	<u>d</u>
Lower Deck Beams & Fastenings	<u>d</u>	Ditto ditto at other places	<u>d</u>	<u>d</u>	Condition, how ascertained	<u>by examination</u>
Planksheers	<u>d</u>	Keelsons	<u>d</u>	<u>d</u>	Sails	<u>3</u>
Sheerstrakes	<u>d</u>	Clamps and Shelves	<u>d</u>	<u>d</u>	Anchors, No. of	<u>3</u>
Topsides	<u>d</u>	Ceiling	<u>d</u>	<u>d</u>	Cables	<u>3</u>
Wales	<u>d</u>	Rudder	<u>d</u>	<u>d</u>	Hawsers and Warps	<u>3</u>
Plank (Bottom) and Counter	<u>d</u>	Copper or V.M. paint	<u>When put on now</u>	<u>d</u>	Standing and Running Rigging	<u>Good</u>
Engine Room Skylights	<u>Good</u>	Caulking of Bottom, Deck, & Waterways	<u>Good</u>	<u>Good</u>	Cargo and Main Hatchways	<u>Good</u>
Coal Bunkers, Openings, Lids, &c.	<u>Good</u>	Scuppers	<u>Good</u>	<u>Good</u>	Hatches	<u>Good</u>

General Observations, Opinion as to Class, &c.
a few rivets in the bottom and keel renewed, butts cemented, Bottom sighted, cleaned and painted. She is now in good and efficient condition, and eligible to remain as classed.

Committee's Minute 24th Dec 1877 Special £1.1.0
 Character assigned 100 A.1 T. Moverly
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) TRW Paid 18