

# ANNUAL SURVEYS.

No. in Reg. Book. **586** No. **1170** Survey held at **London** Date, first Survey **18<sup>th</sup> Dec: 77** Last Survey **11<sup>th</sup> Jan: 78** 1878  
 on the **"Roslin Castle"** Master **Guthrie.**  
 Tonnage **1170** Built at **Glasgow** When built **1863-7 mo**  
 By whom built **Hapsier** Owners **S. Currie & Co.**  
 Port belonging to **Liverpool** Destined Voyage  
 If Surveyed Afloat or in Dry Dock **Canal by Lock**

Last Survey, No. **17983** Port of **Liver**  
 Present Condition of the  
 Decks **Good** Treeneails **Rivets** **Good**  
 Waterways **—** Breasthooks and Stems **—**  
 Comings **—** Transoms, Pointers, and Crutches **—**  
 Upper Deck Beams & Fastenings **—** Timbers of the Frame at the Openings **—**  
 Lower Deck Beams & Fastenings **—** Ditto ditto at other places **—**  
 Planksheers **—** Keelsons **—**  
 Sheerstrakes **—** Clamps and Shelves **—**  
 Topsides **—** Ceiling **—**  
 Vales **—** Rudder **—**  
 Tank (Bottom) and Counter **—** Copper or Y.M. **Cent** When put on  
 Caulking of Bottom, Deck, & Waterways **Good**  
 Windlass and Capstan **Good**  
 Pumps **—**  
 Boats **—**  
 Masts, Yards, &c. **—**  
 Condition, how ascertained **From deck**  
 Sails **Good**  
 Anchors, No. of **3 1/2 18<sup>in</sup> 2 1/2 24<sup>in</sup>**  
 Cables **Good**  
 Hawesers and Warps **—**  
 Standing and Running Rigging **—**  
 Engine Room Skylights **✓** Coal Bunker, Openings, Lids, &c. **✓** Scuppers **Good** Cargo and Main Hatchways **Good** Hatches **Good**  
 General Observations, Opinion as to Class, &c. **Bottom and keel examined, cleaned and coated with Paint & Tallow, and the topsides with Paint.**  
**This Vessel is now in good and efficient condition and in my opinion eligible to remain as classed.**

Committee's Minute **15th January, 1878.**

Character assigned **DPW**

**Thos Wm Blayell.**

Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) **Paid** **18**

No. in Reg. Book. **984** No. **499** Survey held at **London** Date, first Survey **18<sup>th</sup> Dec: 77** Last Survey **28<sup>th</sup> Dec: 77** 1877  
 on the **"Anne Main"** Master **J. W. Swan.**  
 Tonnage **499** Built at **Glasgow** When built **1867-9 mo**  
 By whom built **Stephen** Owners **J. Skinner.**  
 Port belonging to **Glasgow** Destined Voyage  
 If Surveyed Afloat or in Dry Dock **Christ Church Ship.**

Last Survey, No. **15518** Port of **Liver**  
 Present Condition of the  
 Decks **Good** Treeneails **Rivets** **Good**  
 Waterways **—** Breasthooks and Stems **—**  
 Comings **—** Transoms, Pointers, and Crutches **—**  
 Upper Deck Beams & Fastenings **—** Timbers of the Frame at the Openings **—**  
 Lower Deck Beams & Fastenings **—** Ditto ditto at other places **—**  
 Planksheers **—** Keelsons **—**  
 Sheerstrakes **—** Clamps and Shelves **—**  
 Topsides **—** Ceiling **—**  
 Vales **—** Rudder **—**  
 Tank (Bottom) and Counter **—** Copper or Y.M. **Cent** When put on **1867**  
 Caulking of Bottom, Deck, & Waterways **Good**  
 Windlass and Capstan **Good**  
 Pumps **—**  
 Boats **—**  
 Masts, Yards, &c. **—**  
 Condition, how ascertained **From deck**  
 Sails **Good**  
 Anchors, No. of **3 1/2 18<sup>in</sup> 2 1/2 24<sup>in</sup>**  
 Cables **Good**  
 Hawesers and Warps **—**  
 Standing and Running Rigging **—**  
 Engine Room Skylights **✓** Coal Bunker, Openings, Lids, &c. **✓** Scuppers **Good** Cargo and Main Hatchways **Good** Hatches **Good**  
 General Observations, Opinion as to Class, &c. **Bottom and keel examined, cleaned and coated with Paint & Tallow, and the topsides with Paint.**  
**This Vessel is now in good and efficient condition and eligible to remain as classed.**

Committee's Minute **15th January, 1878.**

Character assigned **DPW**

**Thos Wm Blayell.**

Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) **Paid** **18**