

ANNUAL SURVEYS.

No. 25893 Survey held at Liverpool Date, first Survey 11th Dec^r Last Survey 14 Dec^r 1877
 in on the BH. Serica Master Matthew
 Book. 53 Tonnage 913 Built at Dumbarton When built 1875-9
 By whom built M. Millan Owners Flum Main & Montgomerie
 Port belonging to Liverpool Destined Voyage N. Flot C. Ok
 If Surveyed Afloat or in Dry Dock

Last Survey, No. 15186 Port of Liverpool

Classed 100 A1
 Years assigned 9.75
 Character in Register Book.

Present Condition of the
 keels grd Treenails Rivets grd
 Breasthooks and Stemson "
 Transoms, Pointers, and Crutches "
 Timbers of the Frame at the Openings "
 Ditto ditto at other places "
 Keelsons "
 Clamps and Shelves "
 Ceiling "
 Rudder "
 Copper on V.M. Cement When put on 1875
 Caulking of Bottom, Deck, & Waterways grd
 Windlass and Capstan grd
 Pumps "
 Boats "
 Masts, Yards, &c. "
 Condition, how ascertained inspection
 Sails grd
 Anchors, No. of Complete
 Cables "
 Hawser and Warps grd
 Standing and Running Rigging "
 Scuppers grd Cargo and Main Hatchways grd Hatches grd
 General Observations, Opinion as to Class, &c.

This vessel has now been placed in proving dock, the bottom cleaned and painted - is in good condition & eligible in my opinion to remain as classed

Committee's Minute Liverpool Jan^y 11th 1878
 Character assigned 100 A1

Geo. T. Cooper
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18

No. 10 Survey held at Liverpool Date, first Survey 13th Dec^r 77 Last Survey 5 Jan 1878
 in on the S. Bianca Master Griffiths
 Book. 106 Tonnage 1444 Built at Liverpool When built 1862-10
 By whom built Lawrence Owners J. Owen
 Port belonging to Liverpool Destined Voyage Rangoon
 If Surveyed Afloat or in Dry Dock Sandun C. Ok

Last Survey, No. 16475 Port of Liverpool

Classed *A1
 Years assigned 1-76
 Character in Register Book.

Present Condition of the
 keels grd Treenails Rivets grd
 Breasthooks and Stemson "
 Transoms, Pointers, and Crutches "
 Timbers of the Frame at the Openings "
 Ditto ditto at other places "
 Keelsons "
 Clamps and Shelves "
 Ceiling "
 Rudder "
 Copper on V.M. Cement When put on "
 Caulking of Bottom, Deck, & Waterways grd
 Windlass and Capstan grd
 Pumps "
 Boats "
 Masts, Yards, &c. "
 Condition, how ascertained inspection
 Sails Complete
 Anchors, No. of "
 Cables "
 Hawser and Warps "
 Standing and Running Rigging grd
 Scuppers grd Cargo and Main Hatchways grd Hatches grd
 General Observations, Opinion as to Class, &c.

This vessel has now been placed in proving dock - the rudder plating partly re-riveted - the bottom cleaned and painted; is in good condition & eligible in my opinion to remain as classed

Committee's Minute Liverpool Jan^y 11th 1878
 Character assigned *A1

Geo. T. Cooper
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18

Donica

Donica



© 2019

Lloyd's Register
Foundation