

ANNUAL SURVEYS.

No. 25929 Survey held at Liverpool Date, first Survey Jan-4 Last Survey Jan-5 1878
 No. in on the (In) "Jessica" Master Mills
 Reg. Book. 6m Sup Tonnage 293 Built at Greenock When built 1877-5-m
 By whom built Scott Owners J H Goodyear
 Port belonging to Liverpool Destined Voyage S America
 If Surveyed Afloat or in Dry Dock In Canning dry dock

Last Survey, No. 18885 Port of Liverpool Classed 100A-7-77

Present Condition of the Decks Good Treeneils Good
 Waterways " Breasthooks and Stems "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder "
 Plank (Bottom) and Counter " Copper or V.M. Cen When put on 77
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights " Coal Bunker, Openings, Lids, &c. " Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c.

The bottom scraped and painted. This vessel is now in good condition and in my opinion eligible to remain as Classed

Committee's Minute Liverpool Feb 15th 1878 Character assigned 100A
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18

No. 130 Survey held at (In) "Genasserin" Date, first Survey Jan-23 Last Survey Jan-29 1878
 Reg. Book. 130 Tonnage 1413 Built at Belfast Master Balderson
 By whom built 1374 Harland Owners J & J Brocklebank
 Port belonging to Liverpool Destined Voyage India
 If Surveyed Afloat or in Dry Dock Afloat in Great Flood dry dock

Last Survey, No. 18161 Port of Liverpool Classed *A-4-77
J H L 1872-73

Present Condition of the Decks Good Treeneils Good
 Waterways " Breasthooks and Stems "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder "
 Plank (Bottom) and Counter " Copper or V.M. Cen When put on 66
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights " Coal Bunkers, Openings, Lids, &c. " Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c.

The bottom scraped and painted. This vessel is now in good condition and in my opinion eligible to remain as Classed

Committee's Minute Liverpool Feb 15th 1878 Character assigned *A
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18
J H L

Classica

Jorass-erann

25929



© 2019

Lloyd's Register
Foundation