

ANNUAL SURVEYS.

No. in Reg. Book. **25898** Survey held at Liverpool Date, first Survey Dec 19th Last Survey Dec 21st 1877
 on the Bark "Lock-Dee" Master Major
 Tonnage 700 Built at P. Glasgow When built 1870 - 3 mo.
 By whom built P. Glasgow. M. Elch. Owners D & J. Sproat.
 Port belonging to Liverpool Destined Voyage Iquique.
 If Surveyed Afloat or in Dry Dock Brunswick Dry Dock.

Last Survey, No. 17188 Port of Iron Classed S.S. Lu. N^o 1-74. Years assigned. 10.76. Character in Register Book. *A1
 Present Condition of the Decks Good Treenails Rivets Good
 Waterways " Breasthooks and Stems "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shells "
 Topsides " Ceiling "
 Wales " Rudder "
 Plank (Bottom) and Counter " Copper or Y.M. Cement When put on 70
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights ✓ Coal Bunker, Openings, Lids, &c. ✓ Scuppers Good Cargo and Main Hatchways Good Hatches Good

General Observations, Opinion as to Class, &c.
Bottom sighted, cleaned and coated with paint & the vessel being in a good and efficient condition is eligible in my opinion to remain as Classed.

Committee's Minute Liverpool Jan^y 18th 1878.
 Character assigned *A1.

T. Shilstone

Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18

No. in Reg. Book. **216** Survey held at Liverpool Date, first Survey Jan 7/10th Last Survey Jan 7/15th 1878.
 on the Bark "Belle of Benin" Master J. Elliott
 Tonnage 285 Built at Sunderland When built 1875 - 5 mo
 By whom built Gulston Owners J. Harrison & Co.
 Port belonging to Liverpool Destined Voyage Africa
 If Surveyed Afloat or in Dry Dock Queen's Dry Dock.

Last Survey, No. 18858 Port of Iron Classed 100 A1 Years assigned. 7.77. Character in Register Book. *A1
 Present Condition of the Decks Good Treenails Rivets Good
 Waterways " Breasthooks and Stems "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shells "
 Topsides " Ceiling "
 Wales " Rudder "
 Plank (Bottom) and Counter " Copper or Y.M. Cement When put on 75
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights ✓ Coal Bunkers, Openings, Lids, &c. ✓ Scuppers Good Cargo and Main Hatchways Good Hatches Good

General Observations, Opinion as to Class, &c.
Bottom sighted, cleaned and coated with paint, and the vessel being now in a good and efficient condition is eligible in my opinion to remain as Classed.

Committee's Minute Liverpool Jan^y 18th 1878.
 Character assigned 100 A1.

T. Shilstone

Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18

Loch Dee
Bells of Bann
25-898.

