

20121 ANNUAL SURVEYS.

No. 1128 Survey held at London Date, first Survey 3 Jan 1878 Last Survey 8 January 1878
 No. in on the S. Strathblane Master Crawford
 Reg. Book. 1128 Tonnage 1364 Built at Glasgow When built 1868 10 mo
 By whom built Barday Owners J & A. Allan
 Port belonging to Glasgow Destined Voyage
 If Surveyed Afloat or in Dry Dock Blackwall Paint Dry Dock

Last Survey, No. 17436 Port of London
 Present Condition of the
 Decks Good Treasures Rivets Good
 Waterways do Breasthooks and Stemson
 Comings do Transoms, Pointers, and Crutches
 Upper Deck Beams & Fastenings do Timbers of the Frame at the Openings
 Lower Deck Beams & Fastenings do Ditto ditto at other places where
 Planksheers do Keelsons
 Sheerstrakes do Clamps and Shelves
 Topsides do Ceiling seen
 Wgles do Rudder Good
 Plating do Copper or Y.M. Paint When put on now
 Plank (Bottom) and Counter do Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights do Coal Bunker, Openings, Lids, &c. do Scuppers do Cargo and Main Hatchways Good Hatches do
 General Observations, Opinion as to Class, &c.

She is now in a good and efficient condition and eligible in my opinion to remain as classed.

Committee's Minute 22nd January, 1878.
 Character assigned 100A

J. Shearley
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) 18

No. 456 Survey held at London Date, first Survey 7 Jan 1878 Last Survey 8 January 1878
 No. in on the Scw. Br. Glenfinlas Master Milcon
 Reg. Book. 456 Tonnage 1366 Built at Glasgow When built 1874 4 mo
 By whom built 21/1/4 Lm + Glas Co's Owners A B Glas & Co's
 Port belonging to Glasgow Destined Voyage
 If Surveyed Afloat or in Dry Dock Blackwall Paint Dry Dock

Last Survey, No. 17995 Port of London
 Present Condition of the
 Decks Good Treasures Rivets Good
 Waterways do Breasthooks and Stemson
 Comings do Transoms, Pointers, and Crutches
 Upper Deck Beams & Fastenings do Timbers of the Frame at the Openings
 Lower Deck Beams & Fastenings do Ditto ditto at other places where
 Planksheers do Keelsons
 Sheerstrakes do Clamps and Shelves
 Topsides do Ceiling seen
 Wgles do Rudder Good
 Plating do Copper or Y.M. Paint When put on now
 Plank (Bottom) and Counter do Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers do Cargo and Main Hatchways Good Hatches do
 General Observations, Opinion as to Class, &c.

She is now in a good and efficient condition and eligible in my opinion to remain as classed.

Committee's Minute 22nd January, 1878.
 Character assigned 100A

J. Shearley
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) 18