

ANNUAL SURVEYS.

Page 18/2/78

No. in Reg. Book. 1340 No. 4620 Survey held at Hull Date, first Survey 9th Feb Last Survey 8 Feb 1878
 on the "Sir J. G. G. G." Master J. Hunter
 Tonnage 135 1/2 Built at Whitby When built 1845
 By whom built Gunnell Owners W. Gunnell & Co.
 Port belonging to Whitby Destined Voyage Leeds, to load
 If Surveyed Afloat or in Dry Dock Afloat

Last Survey, No. 14864 Port of Iron Classed 90. A. 1.
 Present Condition of the Decks Good Ribs When seen Good
 Waterways do Breasthooks and Stemson do
 Comings do Transoms, Pointers, and Crutches do
 Upper Deck Beams & Fastenings do Timbers of the Frame at the Openings do
 Lower Deck Beams & Fastenings do Ditto ditto at other places do
 Planksheers do Keelsons do
 Sheerstrakes do Clamps and Shelves do
 Topsides do Ceiling do
 Wales do Rudder do
 Plank (Bottom) and Counter do Copper or Y.M. do When put on do
 Engine Room Skylights do Caulking of Bottom, Deck, & Waterways Good
 Coal Bunker, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. Surveyed while lying afloat light, &c.

As far as seen the appears in good and efficient condition, and eligible in my opinion to remain as classed.
 Committee's Minute 19th February, 1878.
 Character assigned 90 A. 1.
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) TRW Paid 18

No. 20 Survey held at Hull Date, first Survey 9th Feb Last Survey 11 Feb 1878
 on the "Sir J. G. G. G." Master Williamson
 Tonnage 226 1/2 Built at Stockton When built 1860
 By whom built Richardson Owners W. Rawson & P. Robinson
 Port belonging to Hull Destined Voyage Barre
 If Surveyed Afloat or in Dry Dock In dry dock & afloat

Last Survey, No. 19341 Port of Iron Classed 90. A. 1.
 Present Condition of the Decks Good Ribs When seen Good
 Waterways do Breasthooks and Stemson do
 Comings do Transoms, Pointers, and Crutches do
 Upper Deck Beams & Fastenings do Timbers of the Frame at the Openings do
 Lower Deck Beams & Fastenings do Ditto ditto at other places do
 Planksheers do Keelsons do
 Sheerstrakes do Clamps and Shelves do
 Topsides do Ceiling do
 Wales do Rudder do
 Plank (Bottom) and Counter do Copper or Y.M. do When put on do
 Engine Room Skylights Good Caulking of Bottom, Deck, & Waterways Good
 Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. Placed on blocks in dry dock and the bottom

cleaned and painted. The appears in good and efficient condition and eligible in my opinion to remain as classed.
 Committee's Minute 19th February, 1878.
 Character assigned 90 A. 1.
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) TRW Paid 18