

REPORT of SURVEY for REPAIRS, &c.

No. in Reg. Book. No. 12049 Survey held at Newcastle Date, first Survey 12th Dec 1877 Last Survey 11th Jan 7 1878

1019 on the Iron S. S. "Annie Ainslie"

Master H. B. Beard

TONNAGE under Tonnage Deck 1314

Ditto of Spar Deck, or Awning Deck

Ditto of Poop

Ditto of Raised Qr. Dk.

Ditto of Houses on Deck

Ditto of Forecastle

Gross Tonnage

Crew Space, as per Rule

Register Tonnage, cut on Beam

Engine Room

Reg. Tons as St^rmer, cut on Bm.

847

Built at Stockton

When built

YEAR.

MONTH.

1870

2

Dec

Owners Nelson, Donkin & Port belonging to

London

Residence Quay-side, Newcastle

By whom built Pearse

Destined Voyage

Surveyed Afloat or in Dry Dock Wallsend Ship

Length of Poop - ft. Ditto, Forecastle - ft.

Ditto, Raised Quarter Deck - ft.

Years assigned.

Character in Register Book.

Last Survey, No. 1915-2

Port Sea

Classed

80A1

REPAIRS, OR EXAMINATION AS PER RULE S. S. N^o 2

S. S. N^o 1-75

The Limbers and ceiling equal to three strakes fore and aft on each side removed, ceiling taken off top of W. B. Tanks, the cement examined and found good, chains ran, windlass examined, and all the requirements of the special survey attended to.

The whole of the inside ironwork including beams and coal bunkers, chipped, cleaned and painted; the water ballast tanks tested satisfactorily to the light line, and the ceiling refitted; pumps and sluices overhauled; masts and rigging overhauled repaired and refitted, deck fittings put in good order, Bottom sighted cleaned and painted.

Present Condition of the

Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Engine Room Skylights

General Observations, Opinion as to Class, &c.

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Transoms

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame at the openings

Ditto Ditto at other places

Keelsons

Clamps and Shelves

Ceiling

Rudder

Copper paint When put on

Caulking of

Bottom, Deck, & Waterways

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Condition, how ascertained

Sails

Anchors No. of

Cables

Hawsers and Warps

Standing & Running Rigging

Cargo and Main Hatchways

Hatches

Good

Good

Good

Good

by examination

Complete

Complete

Complete

Complete

Complete

Complete

Complete

Complete

The Amount of Entry Fee ... £ - : - : - received by me,

Special ... £ 4 : 4 : 0 1878

Certificate (required) ... £ - : - : -

(Travelling Expenses, if any, £ - : - : -)

Committee's Minute

12th February, 1878

Character assigned

2y No 2 on N^o 3

2 12/2/78

80A1

S. S. N^o 3-78

W. M. Moverly

Surveyor to Lloyd's Register of British and Foreign Shipping.

© 2019

Lloyd's Register Foundation

IRON 476 - 008 3