

20211

## Report of Survey for Repairs of Engines and Boilers.

No. 222.

No. in  
Reg. Book. Survey held at

Hamburg

Date, first Survey

15<sup>th</sup> Feb

Last Survey

16<sup>th</sup> Feb

1878

261. on the

S. S. Germania

Master

Krabbe

Tons

433

636

Owners

H. J. Perlback

Port belonging to

Hamburg

Classed

Years  
assigned.

Character in Register Book.

80 A.

576.

Diameter of Cylinder

27<sup>in</sup> x 32<sup>in</sup>

Length of Stroke

33<sup>in</sup>

Engines made at

Hull

When made

1872

Pressure of Steam

65 lbs

Registered Horse Power

110.

By whom made

Humphry &amp; Pearson

## Particulars of Repairs and Examination

The Engines and Boilers have been examined by me, and although they were not taken apart, I saw the Propeller in drydock, also the shafting and all sea cocks and valves, it was a very small repair done to the boilers and few rivets in the front plate renewed all the other parts were in a very good working condition.

The Amount of Fee ... £ 3 : 3 : 0 received by me,  
Certificate (if required) ... £ : : 187 }


(Travelling Expenses, if any, £ )

Committee's Minute

18

Engineer Surveyor to Lloyd's Register of British &amp; Foreign Shipping.

J. A. Liberty

Lloyd's Register  
Foundation

IRON 476-0172

(Condition of Engines and Boilers, and subsequent Repairs and Examinations, to be clearly stated.)

(The Surveyors are requested not to write on or below the space for Committee's Minute.)