

ANNUAL SURVEYS.

No. 20215 Survey held at London Date, first Survey 4th Jan'y Last Survey 4th Jan'y 1876
 No. in on the Ship "Golden Fleece" Master Brown
 Reg. Book. 536 Tonnage 1257 Built at Glasgow When built 1869-6 mo
 By whom built Barclay Owners A. & J. H. Carmichael
 Port belonging to Greenock Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Canal by Lock

Last Survey, No. 17964 Port of London Classed S.S. Lon. No 2-77. Years assigned. 3-77. Character in Register Book. A.1.
 Present Condition of the
 Decks Good Treennails Rivets Good
 Waterways _____ Breasthooks and Stems _____
 Comings _____ Transoms, Pointers, and Crutches _____
 Upper Deck Beams & Fastenings _____ Timbers of the Frame at the Openings _____
 Lower Deck Beams & Fastenings _____ Ditto ditto at other places _____
 Planksheers _____ Keelsons _____
 Sheerstrakes _____ Clamps and Shelves _____
 Topsides _____ Ceiling _____
 Rudder _____
 Copper or Y.M. Cent. When put on 1869
 Caulking of _____
 Bottom, Deck, & Waterways Good
 Windlass and Capstan Good
 Pumps _____
 Boats _____
 Masts, Yards, &c. _____
 Condition, how ascertained From deck
 Sails Good
 Anchors, No. of 312 15 2 1/2
 Cables Good
 Hawsers and Warps do
 Standing and Running Rigging do
 Engine Room Skylights _____ Coal Bunkers, Openings, Lids, &c. _____ Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. Bottom sighted, cleaned and coated with Patent Composition, and the topsides with Paint.

This Vessel is now in good and efficient condition and in my opinion eligible to remain as classed.

Committee's Minute 8th February, 1876.

Character assigned 100A.1

Thos Wm Blayell
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) _____ Paid _____ 18 _____

No. _____ Survey held at London Date, first Survey 22nd Jan'y Last Survey 22nd Jan'y 1876
 No. in on the Ship "Verapis" Master J. C. Dberg
 Reg. Book. 549 Tonnage 1027 Built at Greenock When built 1876-11 mo
 By whom built Scotch Owners W. Lund.
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Britannia by Lock.

Last Survey, No. 17384 Port of London Classed 100A.1. Years assigned. 11-76. Character in Register Book. A.1.
 Present Condition of the
 Decks Good Treennails Rivets Good
 Waterways _____ Breasthooks and Stems _____
 Comings _____ Transoms, Pointers, and Crutches _____
 Upper Deck Beams & Fastenings _____ Timbers of the Frame at the Openings _____
 Lower Deck Beams & Fastenings _____ Ditto ditto at other places _____
 Planksheers _____ Keelsons _____
 Sheerstrakes _____ Clamps and Shelves _____
 Topsides _____ Ceiling _____
 Rudder _____
 Copper or Y.M. Cent. When put on 1876
 Caulking of _____
 Bottom, Deck, & Waterways Good
 Windlass and Capstan Good
 Pumps _____
 Boats _____
 Masts, Yards, &c. _____
 Condition, how ascertained From deck
 Sails Good
 Anchors, No. of 312 15 2 1/2
 Cables Good
 Hawsers and Warps do
 Standing and Running Rigging do
 Engine Room Skylights _____ Coal Bunkers, Openings, Lids, &c. _____ Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. Bottom sighted, cleaned and coated with Patent Composition, and the topsides with Paint.

This Vessel is now in good and efficient condition and in my opinion eligible to remain as classed.

Committee's Minute 8th February, 1876.

Character assigned 100A.1

Thos Wm Blayell
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) _____ Paid _____ 18 _____