

# ANNUAL SURVEYS.

No. 20255 Survey held at London Date, first Survey 22<sup>nd</sup> Jan Last Survey 22<sup>nd</sup> Jan 1878  
 No. in on the Ship "Loch Awe" Master Heir  
 Reg. Book. 592 Tonnage 1053 Built at Glasgow When built 1869 - 4 mo  
 By whom built Barclay Owners J. R. Wilson  
 Port belonging to Glasgow Destined Voyage   
 If Surveyed Afloat or in Dry Dock Canal by Lock

Last Survey, No. 18398 Port of Lon Classed S. S. cl. No 2-77. Years assigned. 5.77. Character in Register Book. #A.1.  
 Present Condition of the  
 Decks Good Treenails Keels Good  
 Waterways .. Breasthooks and Stems ..  
 Comings .. Transoms, Pointers, and Crutches ..  
 Upper Deck Beams & Fastenings .. Timbers of the Frame at the Openings ..  
 Lower Deck Beams & Fastenings .. Ditto ditto at other places not  
 Planksheers .. Keelsons seen  
 Sheerstrakes .. Clamps and Shelves good  
 Topsides .. Ceiling ..  
 Wales .. Rudder ..  
 Plate .. Copper or Y.M. Cent. When put on 1869  
 Plank (Bottom) and Counter .. Caulking of Bottom, Deck, & Waterways good  
 Engine Room Skylights ✓ Coal Bunker, Openings, Lids, &c. ✓ Scuppers good Cargo and Main Hatchways good Hatches good  
 General Observations, Opinion as to Class, &c. Bottom sighted, cleaned and coated with Patent composition and the topsides with Paint.

This vessel is now in good and efficient condition and in my opinion eligible to remain as classed.

Committee's Minute 8th February, 1878.  
 Character assigned \*A.1 DBW

Thos Wm Blasely.  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) Paid 18

No. 20255 Survey held at London Date, first Survey 24<sup>th</sup> Jan Last Survey 24<sup>th</sup> Jan 1878  
 No. in on the Ship "Mairi Bhan" Master J. Mc Arsen.  
 Reg. Book. 161 Tonnage 1315 Built at Glasgow When built 1874 - 3 mo  
 By whom built Barclay Owners P. Mc Intyre  
 Port belonging to London Destined Voyage   
 If Surveyed Afloat or in Dry Dock Milwall by Lock

Last Survey, No. 18075 Port of Lon Classed 100A.1. Years assigned. 9-77. Character in Register Book. #A.1.  
 Present Condition of the  
 Decks Good Treenails Keels Good  
 Waterways .. Breasthooks and Stems ..  
 Comings .. Transoms, Pointers, and Crutches ..  
 Upper Deck Beams & Fastenings .. Timbers of the Frame at the Openings ..  
 Lower Deck Beams & Fastenings .. Ditto ditto at other places ..  
 Planksheers .. Keelsons ..  
 Sheerstrakes .. Clamps and Shelves ..  
 Topsides .. Ceiling ..  
 Wales .. Rudder ..  
 Plate .. Copper or Y.M. Cent. When put on 1874  
 Plank (Bottom) and Counter .. Caulking of Bottom, Deck, & Waterways good  
 Engine Room Skylights ✓ Coal Bunkers, Openings, Lids, &c. ✓ Scuppers good Cargo and Main Hatchways good Hatches good  
 General Observations, Opinion as to Class, &c. Bottom sighted cleaned and coated with Paint and Tallow, and the topsides with Paint.

This vessel is now in good and efficient condition, and in our opinion eligible to remain as classed.

Committee's Minute 8th February, 1878.  
 Character assigned 100A.1 DBW

Thos Wm Blasely.  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) Paid 18