

REPORT of SURVEY for REPAIRS, &c.

(Reed 28. 2. 78.)

Survey held at London Date, first Survey July 22 Last Survey July 27th 1878
 on the SS Londoun Castle Master A. Marshall
 Tonnage under Tonnage Deck 2308 YEAR. MONTH.
 Ditto of Spar Deck, or Awning Deck Built at Glasgow When built 1876 10
 Ditto of Poop Owners J. Skinner & Co Port belonging to Glasgow
 Ditto of Raised Or. Deck Residence
 Ditto of Houses on Deck By whom built Harrison Destined Voyage
 Ditto of Forecastle If Surveyed Afloat or in Dry Dock Dry Dock
 Gross Tonnage 2472
 Crew Space, as per Rule
 Register Tonnage, cut on Beam
 Engine Room
 Reg. Tons as St^rmer, cut on Bm. 1616
 Length of Poop ft. Ditto, Forecastle ft. Ditto, Raised Quarter Deck ft. Years assigned. Character in Register Book.
 Last Survey, No. 17549 Port Swon Classed 100A 1.77

REPAIRS, OR EXAMINATION AS PER RULE

At present owing to damage
Starboard side Renewed 2 plates next the Stern under
the Housepipe.
Bottom coated.

Present Condition of the	<u>Good</u>	Treenails	<u>Good</u>	Windlass and Capstan	
Decks	<u>Good</u>	Rivets	<u>Good</u>	Pumps	
Waterways	<u>Good</u>	Breasthooks and Stemson	<u>Good</u>	Boats	
Comings	<u>Good</u>	Transoms, Pointers, and Crutches	<u>Good</u>	Masts, Yards, &c.	<u>Good & sufficient</u>
Upper Deck Beams & Fastenings	<u>Good</u>	Timbers of the Frame at the openings	<u>Good</u>	Condition, how ascertained	<u>where</u>
Lower Deck Beams & Fastenings	<u>Good</u>	Ditto Ditto at other places	<u>Good</u>	Sails	<u>where</u>
Planksheers	<u>Good</u>	Keelsons	<u>Good</u>	Anchors No. of <u>3 B. 12 1/2</u>	<u>where</u>
Sheerstrakes	<u>Good</u>	Clamps and Shelves	<u>Good</u>	Cables	<u>where</u>
Topsides	<u>Good</u>	Ceiling	<u>Good</u>	Hawsers and Warps	<u>where</u>
Wales	<u>Good</u>	Rudder	<u>Good</u>	Standing & Running Rigging	
Plank (Bottom) and Counter	<u>Good</u>	Copper <u>broken</u> When put on <u>Good</u>		Cargo and Main Hatchways	<u>Good</u>
Engine Room Skylights	<u>Good</u>	Caulking of	<u>Good</u>	Hatches	<u>Good</u>
Coal Bunker, Openings, Lids, &c.	<u>Good</u>	Bottom, Deck, & Waterways	<u>Good</u>		
General Observations, Opinion as to Class, &c.		Scuppers	<u>Good</u>		

She is now in good condition
and entitled to remain as classed.

The Amount of Entry Fee ... £ ...
 13/78 Special ... £ 2 : 2 :
 Certificate (if required) ... £ 5 :
 (Travelling Expenses, if any, £)

Committee's Minute 5th March, 1878.

Character assigned

100A 1
DBW

George Martindale
J. P. Kearns

Surveyor to Lloyd's Register of British and Foreign Shipping.



© 2019

Lloyd's Register Foundation

IRON 476-0241