

20214 36.9 58
REPORT of SURVEY for REPAIRS, &c. (Recd 11.2.78)

No. Survey held at London Date, first Survey Feb 2 Last Survey Feb 5th 1878
on the SS Malaga Master
Tonnage under Tonnage Deck 1420
of Spar Deck, or Awning Deck
of Poop
of Raised Qr. Dk.
of Houses on Deck
of Forecastle
Tonnage 1614
Space, as per Rule
er Tonnage, cut on Beam
e Room
Tons as St' mer, cut on Bm. 1024
of Poop 40 ft. Ditto, Forecastle 33 $\frac{1}{2}$ ft. Ditto, Raised Quarter Deck ft.
Survey, No. 18893 Port Iron
Classed 100A 7.77

RS, OR EXAMINATION AS PER RULE

Owing to Damage.
Portside. Main Channel Bars all been taken & repaired.
replaced & rivetted. Main Rail at Main Rigging repaired with 83 feet
New Main Wire Rigging also topmast & top gallant stays.
one new plate on Deck House round Gunwale (on side)
Boats Iron Sails repaired.

Condition of the

Good	Treenails	Rivets	Good	Windlass and Capstan	
Good	Breasthooks and Stemson		Good	Pumps	
Good	Transoms, Pointers, and Crutches		Good	Boats 6	
Good	Timbers of the Frame at the openings		Good	Masts, Yards, &c.	Good &
Good	Ditto Ditto at other places		Good	Condition, how ascertained	Sufficient
Good	Keelsons		Good	Sails	where
Good	Clamps and Shelves		Good	Anchors No. of 3 Bns. 14 & 12 lbs	they
Good	Ceiling		Good	Cables	could
Good	Rudder		Good	Hawsers and Warps	be seen
Good	Copper	When put on	Good	Standing & Running Rigging	
Good	Caulking of		Good		
Good	Bottom, Deck, & Waterways		Good		
Good	Room Skylights	Good	Good	Cargo and Main Hatchways	Good
Good	Coal Bunker, Openings, Lids, &c.	Good	Good	Hatches	Good
Good	Scuppers	Good	Good		

Observations, Opinion as to Class, &c.

She is now in good condition
and entitled to remain as classed

Senhouse Masterman

Amount of Entry Fee ... £ ...
12/12/78 Special ... £ / : / :
Certificate (if required) ... £ : 5 :
Expenses, if any, £)

Committee's Minute

15th February, 1878,

Character assigned

100A
DW

Surveyor to Lloyd's Register of British and Foreign Shipping.



© 2019

Lloyd's Register
Foundation

IRON476-0247