

20271
REPORT of SURVEY for REPAIRS, &c.

No. *4259* Survey held at *Cardiff* Date, first Survey _____ Last Survey *1 Feb'y* 18*78*
Reg. Book. _____ Master *Jagmes*
on the *S.S. Mercury* YEAR. MONTH.
TONNAGE under Tonnage Deck *881* Built at *Newcastle* When built *1864*
Ditto of Spar Deck, or Awning Deck _____ Owners *Hall Bros* Port belonging to *Newcastle*
Ditto of Poop _____ Residence *Newcastle*
Ditto of Raised Qr. Dk _____ By whom built *Palmer* Destined Voyage _____
Ditto of Houses on Deck _____ If Surveyed ~~Afloat~~ or in Dry Dock *Newport Dry Dock*
Ditto of Forecastle _____
Gross Tonnage *884*
Crew Space, as per Rule _____
Register Tonnage, cut on Beam _____
Engine Room _____
Reg. Tons as St' mer, cut on Bm. *555*
Length of Poop _____ ft. Ditto, Forecastle _____ ft. Ditto, Raised Quarter Deck _____ ft.
Last Survey, No. *1808* Port *Leam* Classed *C 1*
SS No. *3. 177*

REPAIRS, OR EXAMINATION AS PER RULE

Placed on blocks in Dry Dock Bottom well cleaned, and coated -
Rudder lifted Riggers repasted and some bolts renewed in after
bearing of Propeller Shaft. Two Strops fitted on Foremast Head
Topgallant Reels, and Bulwarks repaired, and Landing Deck fittings
made good

Present Condition of the Decks	<i>Good</i>	<i>Pilots</i>	<i>Good</i>	Windlass and Capstan	
Waterways	<i>"</i>	<i>Treenails</i> <i>phoresen</i>	<i>"</i>	Pumps	
Comings	<i>"</i>	Breasthooks and Stems	<i>"</i>	Boats	<i>so far</i>
Upper Deck Beams & Fastenings	<i>"</i>	Transoms, Pointers, and Crutches	<i>"</i>	Masts, Yards, &c.	<i>as</i>
Lower Deck Beams & Fastenings	<i>"</i>	Timbers of the Frame at the openings	<i>"</i>	Condition, how ascertained	<i>seen</i>
Planksheers	<i>"</i>	Ditto Ditto at other places	<i>"</i>	Sails	
Sheerstrakes	<i>"</i>	Keelsons	<i>"</i>	Anchors No. of	<i>Good</i>
Topsides <i>Plating</i>	<i>"</i>	Clamps and Shelves <i>Stringers</i>	<i>"</i>	Cables	<i>and</i>
Wales	<i>"</i>	Ceiling	<i>"</i>	Hawsers and Warps	<i>offt</i>
Plank (Bottom) and Counter	<i>"</i>	Rudder	<i>"</i>	Standing & Running Rigging	
		Copper <i>Paint</i> When put on <i>now</i>			
		Caulking of			
		Bottom, Deck, & Waterways			
Engine Room Skylights		Coal Bunker, Openings, Lids, &c.	Scuppers	Cargo and Main Hatchways	Hatches

General Observations, Opinion as to Class, &c.

so far as seen the vessel is in efficient condition, eligible to
remain as classed C 1

The Amount of Entry Fee ... £ : : received by me, *A. J. J.*
Special ... £ / : : *18/2* 1878
Certificate (if required) ... £ : :
(Travelling Expenses, if any, £)

Committee's Minute 26th February, 1878.

Character assigned *C 1*

Henry J. Pyrell
Surveyor to Lloyd's Register of British and Foreign Shipping.



© 2019

Lloyd's Register Foundation

IRON476 -0256

Mercury



© 2019

Lloyd's Register
Foundation