

ANNUAL SURVEYS.

No. in Reg. Book. **247** No. **25941** Survey held at **Liverpool** Date, first Survey **Jan 28th** Last Survey **Jan 29th** 1878
 on the Ship **"Pendragon"** Master **S. Morrish**
 Tonnage **1278** Built at **Liverpool** When built **1868 - 3 mo**
 By whom built **Royden** Owners **McDiarmid Greenshield & Co.**
 Port belonging to **Liverpool** Destined Voyage
 If Surveyed Afloat or in Dry Dock **Brunswick Dry Dock**

Last Survey, No. **17473** Port of **Liverpool** Classed **S.S. Lon N^o 2. 76.** Years assigned. **11. 76.** Character in Register Book. **A1**
 Present Condition of the Decks **Good** Greenails **Rivets** **Good**
 Waterways **Good** Breasthooks and Stomson **Good**
 Comings **Good** Transoms, Pointers, and Crutches **Good**
 Upper Deck Beams & Fastenings **Good** Timbers of the Frame at the Openings **Good**
 Lower Deck Beams & Fastenings **Good** Ditto ditto at other places **Good**
 Planksheers **Good** Keelsons **Good**
 Sheerstrakes **Good** Clamps and Shells **Good**
 Topsides **Good** Ceiling **Good**
 Wales **Good** Rudder **Good**
 Plank (Bottom) and Counter **Good** Copper or Y.M. **Cement** When put on **1868**
 Caulking of Bottom, Deck, & Waterways **Good**
 Engine Room Skylights **✓** Coal Bunker, Openings, Lids, &c. **✓** Scuppers **Good** Cargo and Main Hatchways **Good** Hatches **Good**
 General Observations, Opinion as to Class, &c.

Bottom sighted, cleaned and coated with paint, and the vessel being now in a good & efficient condition is eligible in my opinion to remain as Classed.

Committee's Minute **Liverpool Feb 22 - 1878.**
 Character assigned ***A1.**

T. Shilston.
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) **18**

No. in Reg. Book. **340** No. **25941** Survey held at **Liverpool** Date, first Survey **Jan 24th** Last Survey **Jan 24th** 1878
 on the Ship **"Bertram Rigby"** Master **T. Thomas.**
 Tonnage **1284** Built at **Stull** When built **1864 - 4 mo**
 By whom built **Earle** Owners **E. Bates & Sons**
 Port belonging to **Liverpool** Destined Voyage **San Francisco.**
 If Surveyed Afloat or in Dry Dock **Queen's Dry Dock**

Last Survey, No. **17408** Port of **Liverpool** Classed **S.S. Lon N^o 3. 76.** Years assigned. **10. 76.** Character in Register Book. **A1**
 Present Condition of the Decks **Good** Greenails **Rivets** **Good**
 Waterways **Good** Breasthooks and Stomson **Good**
 Comings **Good** Transoms, Pointers, and Crutches **Good**
 Upper Deck Beams & Fastenings **Good** Timbers of the Frame at the Openings **Good**
 Lower Deck Beams & Fastenings **Good** Ditto ditto at other places **Good**
 Planksheers **Good** Keelsons **Good**
 Sheerstrakes **Good** Clamps and Shells **Good**
 Topsides **Good** Ceiling **Good**
 Wales **Good** Rudder **Good**
 Plank (Bottom) and Counter **Good** Copper or Y.M. **Cement** When put on **64.**
 Caulking of Bottom, Deck, & Waterways **Good**
 Engine Room Skylights **✓** Coal Bunkers, Openings, Lids, &c. **✓** Scuppers **Good** Cargo and Main Hatchways **Good** Hatches **Good**
 General Observations, Opinion as to Class, &c.

Bottom sighted, cleaned and coated with paint, and the vessel being now in a good and efficient condition is eligible in my opinion to remain as Classed.

Committee's Minute **Liverpool Feb 22 - 1878.**
 Character assigned ***A1.**

T. Shilston.
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) **18**

1820-9476-020

*Condensation
of the
Portland City*

25941.



© 2019

Lloyd's Register
Foundation