

ANNUAL SURVEYS.

20206.

Rec 23/1/78

No. in Reg. Book. 247 No. 25941 Survey held at Liverpool Date, first Survey Jan 28th Last Survey Jan 29th 1878
 on the Ship "Pendragon" Master J. Morrish
 Tonnage 1278 Built at Liverpool When built 1868 - 3 mo
 By whom built Royden Owners McDiarmid Greenshield & Co.
 Port belonging to Liverpool Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Brunswick Dry Dock

Present Condition of the Decks	Good	Greenails	Rivets	Good	Classed	S.S. Lon N ^o . 2. 76.	Years assigned.	Character in Register Book.
Waterways	✓	Breasthooks and Stomson	✓	✓	S.S. Lon N ^o . 2. 76.	11.76.	*	A1
Comings	✓	Transoms, Pointers, and Crutches	✓	✓				
Upper Deck Beams & Fastenings	✓	Timbers of the Frame at the Openings	✓	✓	Pumps	✓		
Lower Deck Beams & Fastenings	✓	Ditto ditto at other places	✓	✓	Boats	✓		
Plank sheers	✓	Keelsons	✓	✓	Masts, Yards, &c.	✓		
Sheerstrakes	✓	Clamps and Shells	✓	✓	Condition, how ascertained	from on board		
Topsides	✓	Ceiling	✓	✓	Sails	Good		
Wales	✓	Rudder	✓	✓	Anchors, No. of	3B - 1S - 2K		
Plank (Bottom) and Counter	✓	Copper or Y.M. Cement When put on	1868	✓	Cables	part seen	Good	
Engine Room Skylights	✓	Caulking of Bottom, Deck, & Waterways	Good	✓	Hawsers and Warps	and		
Coal Bunker, Openings, Lids, &c.	✓	Scuppers	Good	✓	Standing and Running Rigging	Sufficient		
Cargo and Main Hatchways	✓	Hatches	Good	✓		Good		

General Observations, Opinion as to Class, &c.
Bottom sighted, cleaned and coated with paint, and the vessel being now in a good & efficient condition is eligible in my opinion to remain as Classed.

Committee's Minute Liverpool Feb 22nd - 1878.
 Character assigned *A1.
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) _____ Paid _____ 18 _____

No. in Reg. Book. 340 No. _____ Survey held at Liverpool Date, first Survey Jan 24th Last Survey Jan 24th 1878
 on the Ship "Bertram Rigby" Master J. Thomas
 Tonnage 1284 Built at Null When built 1864 - 4 mo
 By whom built Earle Owners E. Bates & Sons
 Port belonging to Liverpool Destined Voyage San Francisco.
 If Surveyed Afloat or in Dry Dock Queen's Dry Dock

Present Condition of the Decks	Good	Greenails	Rivets	Good	Classed	S.S. Lon N ^o . 3. 76.	Years assigned.	Character in Register Book.
Waterways	✓	Breasthooks and Stomson	✓	✓	S.S. Lon N ^o . 3. 76.	10.76.	*	A1
Comings	✓	Transoms, Pointers, and Crutches	✓	✓				
Upper Deck Beams & Fastenings	✓	Timbers of the Frame at the Openings	✓	✓	Pumps	✓		
Lower Deck Beams & Fastenings	✓	Ditto ditto at other places	✓	✓	Boats	✓		
Plank sheers	✓	Keelsons	✓	✓	Masts, Yards, &c.	✓		
Sheerstrakes	✓	Clamps and Shells	✓	✓	Condition, how ascertained	from on board		
Topsides	✓	Ceiling	✓	✓	Sails	Good		
Wales	✓	Rudder	✓	✓	Anchors, No. of	3B - 1S - 2K		
Plank (Bottom) and Counter	✓	Copper or Y.M. Cement When put on	64.	✓	Cables	part seen	Good	
Engine Room Skylights	✓	Caulking of Bottom, Deck, & Waterways	Good	✓	Hawsers and Warps	and		
Coal Bunkers, Openings, Lids, &c.	✓	Scuppers	Good	✓	Standing and Running Rigging	Sufficient		
Cargo and Main Hatchways	✓	Hatches	Good	✓		Good		

General Observations, Opinion as to Class, &c.
Bottom sighted, cleaned and coated with paint, and the vessel being now in a good and efficient condition is eligible in my opinion to remain as Classed.

Committee's Minute Liverpool Feb 22nd - 1878.
 Character assigned *A1.
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) _____ Paid _____ 18 _____



1820-9474-021

Pendragon
Boston City

25941.



© 2019

Lloyd's Register
Foundation