

ANNUAL SURVEYS. 20344

No. in Reg. Book. on the **No. 4614** Survey held at **Hull** Date, first Survey **11th Jan'y** Last Survey **18th Jan'y** 18**48**
88 on the **Snow BR "Warrior"** Master **Thompson**
 Tonnage **484** Built at **Stockton** When built **1858**
 By whom built **500** Owners **J. Thomas**
 Port belonging to **Liverpool** Destined Voyage **South America via Lyne**
 If Surveyed Afloat or in Dry Dock **In fibrous dry dock & afloat in Victoria BR**

Last Survey, No. **14437** Port of **Liverpool**

Classed

Years assigned. Character in Register Book.

Present Condition of the Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Engine Room Skylights

Coal Bunker, Openings, Lids, &c.

General Observations, Opinion as to Class, &c.

Treenails **five**

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame at the Openings

Ditto ditto at other places

Keelsons

Clamps and Shelves

Ceiling

Rudder

Copper or Y.M.

When put on

Caulking of

Bottom, Deck, & Waterways

Scuppers

Cargo and Main Hatchways

Hatches

S.S. Liv No. 3-46

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Condition, how ascertained **by enquiry &c**

Sails

Anchors, No. of **3 B. 1 C. 1**

Cables

Hawsers and Warps

Standing and Running Rigging

now done. Bottom cleaned and painted.

Two Redge anchors required to be supplied, stated to be supplied at the Lyne. Is eligible in my opinion to remain as classed *A1 when Redge anchors are supplied

Committee's Minute

15th February,

1848.

Character assigned

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required)

Paid

18

No.

Survey held at

Date, first Survey

Last Survey

18

No. in Reg. Book. on the

Master

Tonnage

Built at

When built

By whom built

Owners

Port belonging to

Destined Voyage

If Surveyed Afloat or in Dry Dock

Last Survey, No.

Port of

Classed

Years assigned.

Character in Register Book.

Present Condition of the

Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Engine Room Skylights

Coal Bunkers, Openings, Lids, &c.

Scuppers

Cargo and Main Hatchways

Hatches

General Observations, Opinion as to Class, &c.

Treenails

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame at the Openings

Ditto ditto at other places

Keelsons

Clamps and Shelves

Ceiling

Rudder

Copper or Y.M.

When put on

Caulking of

Bottom, Deck, & Waterways

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Condition, how ascertained

Sails

Anchors, No. of

Cables

Hawsers and Warps

Standing and Running Rigging

Committee's Minute

18

Character assigned

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required)

Paid

18