

20346
26996

ANNUAL SURVEYS.

Recd 16.2.78

No. in Reg. Book. **273** No. **1** Survey held at London Date, first Survey 31st Jan'y Last Survey 1st Feby 1878
 on the S.S. "Widgeon" Master J. Key
 Tonnage 503 Built at Newcastle When built 1876-3 mo.
 By whom built Mcitchell Owners Gen. Str. Nav. Co.
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Leptford Green by Locks.

Last Survey, No. 16466 Port of Iron Classed _____ Years assigned. _____ Character in Register Book. 100 A.1.
5-76.

Present Condition of the Decks	<u>good</u>	Treenails	<u>Rivets</u>	<u>good</u>	Windlass and Capstan	<u>good</u>
Waterways	---	Breasthooks and Stems	---	---	Pumps	---
Comings	---	Transoms, Pointers, and Crutches	---	---	Boats	---
Upper Deck Beams & Fastenings	---	Timbers of the Frame at the Openings	---	---	Masts, Yards, &c.	---
Lower Deck Beams & Fastenings	---	Ditto ditto at other places	---	---	Condition, how ascertained	<u>From deck</u>
Planksheers	---	Keelsons	---	---	Sails	<u>good</u>
Sheerstrakes	---	Clamps and Shelves	---	---	Anchors, No. of	<u>3 B's 15th 2 1/2 age</u>
Topsides	---	Ceiling	---	---	Cables	<u>240 Faths good</u>
Wales	---	Rudder	---	---	Hawsers and Warps	<u>and</u>
Plank (Bottom) and Counter	---	Copper or Y.M. Cement When put on	<u>1876</u>	---	Standing and Running Rigging	<u>sufficient</u>
Engine Room Skylights	<u>good</u>	Caulking of Bottom, Deck, & Waterways	<u>good</u>	---	Cargo and Main Hatchways	<u>good</u>
Coal Bunker, Openings, Lids, &c.	<u>good</u>	Scuppers	<u>good</u>	---	Hatches	<u>good</u>

General Observations, Opinion as to Class, &c. Bottom and keel sighted, Chain cables ranged on deck, bottom coated with black Varnish.

This vessel is now in good and efficient condition and in my opinion eligible to remain as classed.

Committee's Minute 22nd February, 1878. Thos Wm Blayell.
 Character assigned 100 A.1 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) _____ Paid _____ 18 _____

No. in Reg. Book. **354** No. **1** Survey held at London Date, first Survey 9th Jan'y Last Survey 12th Feby 1878
 on the S.S. "Volmer" Master H. L. Hansen
 Tonnage 1331 Built at Copenhagen When built 1875-8 mo
 By whom built Birmister Owners Carls Stm Ship Co.
 Port belonging to Copenhagen Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Britannia by Locks

Last Survey, No. 17687 Port of Iron Classed _____ Years assigned. _____ Character in Register Book. 90 A.1.
1-77

Present Condition of the Decks	<u>good</u>	Treenails	<u>Rivets</u>	<u>good</u>	Windlass and Capstan	<u>good</u>
Waterways	---	Breasthooks and Stems	---	---	Pumps	---
Comings	---	Transoms, Pointers, and Crutches	---	---	Boats	---
Upper Deck Beams & Fastenings	---	Timbers of the Frame at the Openings	---	---	Masts, Yards, &c.	---
Lower Deck Beams & Fastenings	---	Ditto ditto at other places	---	---	Condition, how ascertained	<u>From deck.</u>
Planksheers	---	Keelsons	---	---	Sails	<u>good</u>
Sheerstrakes	---	Clamps and Shelves	---	---	Anchors, No. of	<u>3 B's 15th 2 1/2 age</u>
Topsides	---	Ceiling	---	---	Cables	<u>good</u>
Wales	---	Rudder	---	---	Hawsers and Warps	<u>do</u>
Plank (Bottom) and Counter	---	Copper or Y.M. Cement When put on	<u>1876</u>	---	Standing and Running Rigging	<u>do</u>
Engine Room Skylights	<u>good</u>	Caulking of Bottom, Deck, & Waterways	<u>good</u>	---	Cargo and Main Hatchways	<u>good</u>
Coal Bunkers, Openings, Lids, &c.	<u>good</u>	Scuppers	<u>good</u>	---	Hatches	<u>good</u>

General Observations, Opinion as to Class, &c. Bottom and keel sighted, several defective rivets in Port bow taken out and renewed, bottom coated with Paint.

This vessel is now in good and efficient condition, and in my opinion eligible to remain as classed.

Committee's Minute 22nd February, 1878. Thos Wm Blayell.
 Character assigned 90 A.1 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) _____ Paid _____ 18 _____