

ANNUAL SURVEYS.

No. 25959 Survey held at Liverpool Date, first Survey July 9th Last Survey July 16th 1878
 No. in on the (Lon) Bre Craigair Master J. Rae
 Reg. Book. 406 Tonnage 601 Built at P. Glasgow When built 1875-1 mo
 By whom built Funcan Owners A. Rae
 Port belonging to Liverpool Destined Voyage America
 If Surveyed Afloat or in Dry Dock Afloat & in Canning dry dock
 Last Survey, No. 14650 Port of Liverpool Classed 100 A1-1-77

Present Condition of the
 Decks Good Treasures Ports — Good
 Waterways " Breasthooks and Stenson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder "
 Plates (Bottom) and Counter " Copper or Y.M. Cen When put on 75
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights " Coal Bunker, Openings, Lids, &c. " Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. Good & efficient
See from deck
Good
efficient
Good

The bottom scraped & painted - This vessel is now in good condition and in my opinion eligible to remain as Classed

Committee's Minute Liverpool March 12th 1878
 Character assigned 100 A1.

E. B. Wheeler
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18

No. 22 Survey held at Liverpool Date, first Survey July 27th Last Survey March 6th 1878
 No. in on the (Lon) "Victoria Nyamra" Master Large
 Reg. Book. 22 Tonnage 1022 Built at Belfast When built 1863-8
 By whom built Harland Owners G. H. Fletcher
 Port belonging to Liverpool Destined Voyage San Francisco
 If Surveyed Afloat or in Dry Dock Afloat & in Canning dry dock
 Last Survey, No. 14499 Port of Liverpool Classed *A1-12-76
See from deck
See from deck
See from deck

Present Condition of the
 Decks Good Treasures Ports — Good
 Waterways " Breasthooks and Stenson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder "
 Plates (Bottom) and Counter " Copper or Y.M. Cen When put on 74
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights " Coal Bunkers, Openings, Lids, &c. " Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. Good & efficient
See from deck
Good
efficient
Good

The bottom scraped & painted - This vessel is now in good condition and in my opinion eligible to remain as Classed

Committee's Minute Liverpool March 12th 1878
 Character assigned *A1.

E. B. Wheeler
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18

Guignard
Historica Sepanba
25909



© 2019

Lloyd's Register
Foundation