

# REPORT of SURVEY for REPAIRS, &c.

No. 11885

No. in  
Reg. Book.

Survey held at Sunderland.

Date, first Survey 4<sup>th</sup> February Last Survey 4<sup>th</sup> February 1878.

on the Iron S.S. Medusa

Master A. Wright

TONNAGE under Tonnage Deck 1110

YEAR.

MONTH.

Ditto of Spar Deck, or Awning Deck

Built at Sunderland

When built 1882 (17<sup>th</sup>)

Ditto of Poop

Owners James Laing

Port belonging to Sunderland

Ditto of Raised Qr. Dk.

Ditto of Houses on Deck

Residence Thornhill, Sunderland

Ditto of Forecastle

Gross Tonnage

1110

Crew Space, as per Rule

By whom built James Laing

Destined Voyage —

Register Tonnage, out on Beam

Engine Room

Reg. Tons as St<sup>r</sup>mer, cut on Bm.

719

If Surveyed Afloat or in Dry Dock At Laing's Dry Dock

Length of Poop

ft.

Ditto, Forecastle

ft.

Ditto, Raised Quarter Deck

ft.

Years assigned.

Character in Register Book.

Last Survey, No. 11885

Port Sunderland

Load line 17 ft Awning Decked

Classed

90 A. I.

REPAIRS, OR EXAMINATION AS PER RULE for Annual Survey

Now done: The vessel placed in dry dock. the bottom

sighted, scraped and painted with two coats of paint.

Examined the condition of the Caulking of the

Awning deck and made it good where requisite.

This vessel's side is marked in the manner described by the Committee's Circular No. 354, to the height of the load line 17 feet.

Present Condition of the

Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Plating of Plank sheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Engine Room Skylights

General Observations, Opinion as to Class, &c.

Keels  
Treenails

Breasthooks and Stems

Transoms, Pointers, and Grutches

Timbers of the Frame at the openings

Ditto Ditto at other places

Keelsons

Clamps and Shelves

Ceiling

Rudder

Copper Paint When put on

Caulking of Bottom, Deck, & Waterways

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Condition, how ascertained

Sails

Anchors No. of

Cables

Hawsers and Warps

Standing & Running Rigging

Cargo and Main Hatchways

Hatches

The Amount of Entry Fee ...

received by me,

Special ...

187

Certificate (if required) ...

(Travelling Expenses, if any, £ ...)

Committee's Minute

19<sup>th</sup> March,

1878.

Character assigned

Surveyor to Lloyd's Register of British and Foreign Shipping.



© 2019

Lloyd's Register Foundation

IRON471-0133