

ANNUAL SURVEYS.

205-3

37.077

Recd 21. 2. 78
July 11th 1878

No. in Reg. Book. 1040 No. 1040 Survey held at London Date, first Survey 1871 Last Survey July 11th 1878
on the SS Mesopotamia Master J Phillips
Tonnage 765 Built at Renfrew When built 1871 GM
By whom built Henderson Owners Lynch & Co.
Port belonging to London Destined Voyage
If Surveyed Afloat or in Dry Dock By SR

Last Survey, No. 19507 Port of London

Years assigned. 90AL 10.77
Character in Register Book. SS Lm ML 75

Present Condition of the Decks <u>Good</u>	Treenails <u>Rivets</u> <u>Good</u>	Windlass and Capstan <u></u>
Waterways <u>"</u>	Breasthooks and Stemson <u>"</u>	Pumps <u></u>
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>"</u>	Boats <u></u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame at the Openings <u>"</u>	Masts, Yards, &c. <u>Good &</u>
Lower Deck Beams & Fastenings <u>"</u>	Ditto ditto at other places <u>"</u>	Condition, how ascertained <u>Sufficient</u>
Planksheers <u>"</u>	Keelsons <u>"</u>	Sails <u>when</u>
Sheerstrakes <u>"</u>	Clamps and Shelves <u>"</u>	Anchors, No. of <u>3 No. 12 1/2 inch</u> <u>they</u>
Topsides <u>"</u>	Ceiling <u>"</u>	Cables <u>could</u>
Wales <u>"</u>	Rudder <u>"</u>	Hawsers and Warps <u>be seen</u>
Plank (Bottom) and Counter <u>"</u>	Copper or <u>F.M. Coated</u> When put on <u>new</u>	Standing and Running Rigging <u></u>
Engine Room Skylights <u>Good</u>	Caulking of Bottom, Deck, & Waterways <u>Good</u>	
Coal Bunker, Openings, Lids, &c. <u>Good</u>	Scuppers <u>Good</u>	Cargo and Main Hatchways <u>Good</u>
General Observations, Opinion as to Class, &c. <u>She is now in good condition and entitled to remain as classed</u>		Hatches <u>Good</u>

Committee's Minute

Character assigned

5/3 1878

Lloyd's Register

Senhouse Martin

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required) Paid 18

IRON 477-0135

Meophotomio
Prestat bottle



© 2019

Lloyd's Register
Foundation