

203-73-
REPORT of SURVEY for REPAIRS, &c.

No. 1980

No. in
Reg. Book.

Survey held at Middlesbrough

Date, first Survey 21st Feb^r

Last Survey 8th March 1878

on the Iron screw Steamer "Monaco"

Master B. J. Lee

YEAR.

MONTH.

TONNAGE under Tonnage Deck

Ditto of Spar Deck, or Awning Deck

Ditto of Poop

Ditto of Raised Qr. Dk.

Ditto of Houses on Deck

Ditto of Forecastle

Gross Tonnage

Crew Space, as per Rule

Register Tonnage, cut on Beam

Engine Room

Reg. Tons as St^rmer, cut on Bm.

Built at

S. Shields

When built

1875

10

Owners

Dansey & Robinson

Port belonging to

S. Shields

Residence

20. George Stⁿ - Greenwich

By whom built

Readhead & Co

Destined Voyage

If Surveyed Afloat or in Dry Dock

Shipping

Length of Poop

ft. Ditto, Forecastle

ft. Ditto, Raised Quarter Deck

ft.

Years
assigned.

Character in Register Book.

Classed

100-1

Last Survey, No.

19004

Port

Lion

REPAIRS, OR EXAMINATION AS PER RULE

through damage

Renewed two garboard and three shell plates on the S^e side and one on the
Port side & seven angle irons of the frames strengthened with 7 lengths of angle
iron. About 2000 rivets renewed in the bottom. The cement relaid in fore hold
and bottom recoated with paint.

Present Condition of the

Decks

good

Waterways

do

Comings

do

Upper Deck Beams & Fastenings

do

Lower Deck Beams & Fastenings

do

Planksheers

Sheerstrakes

Topsides

do

Wales

do

Plank (Bottom) and Counter

do

Rivets
Fresnails

good

Breasthooks and Stenson

do

Transoms, Pointers, and Crutches

do

Timbers of the Frame at the openings

do

Ditto Ditto at other places

do

Keelsons

do

Clamps and Shells

Ceiling

do

Rudder

do

Copper

When put on

1875

Caulking of

Bottom, Deck, & Waterways

good

Winlass and Capstan

good

Pumps

do

Boats

do

Masts, Yards, &c.

do

Condition, how ascertained

from deck

Sails

good

Anchors No. of

do

Cables

do

Hawsers and Warps

do

Standing & Running Rigging

do

Engine Room Skylights good Coal Bunker, Openings, Lids, &c. good Scuppers good Cargo and Main Hatchways good Hatches good

General Observations, Opinion as to Class, &c. This vessel is in a good and efficient state of

repair fit for the safe conveyance of dry and perishable goods and is
liable, in my opinion, to remain as classed.

The Amount of Entry Fee ...

£ 2

: "

: "

: "

received by me,

Special

£ 3

: "

: "

: "

8th April 1878

Certificate (if required) ...

£ "

: "

: "

: "

(Travelling Expenses, if any, £)

Committee's Minute

12th April

1878

Character assigned

100A

T. W.

Surveyor to Lloyd's Register of British and Foreign Shipping.



© 2019

Lloyd's Register
Foundation

IRON477-0139