

ANNUAL SURVEYS.

No. in Reg. Book. on the *Ship "Mountaineer"* Survey held at *Liverpool* Date, first Survey *Mar 2nd* Last Survey *Mar 5th* 1878
 1339. Tonnage *1496* Built at *Sunderland* When built *1875 - 1 mo.*
 By whom built *Ritchie* Owners *G. N. Gardiner & Co.*
 Port belonging to *Liverpool.* Destined Voyage *Melbourne*
 If Surveyed Afloat or in Dry Dock *Brunswick Dry Dock*

Last Survey, No. *27126* Port of *Liver* Classed *100 AI*
 Present Condition of the Decks *Good* Treanails *Rivets.* *Good*
 Waterways *"* Breasthooks and Stems *"*
 Comings *"* Transoms, Pointers, and Crutches *"*
 Upper Deck Beams & Fastenings *"* Timbers of the Frame at the Openings *"*
 Lower Deck Beams & Fastenings *"* Ditto ditto at other places *"*
 Planksheers *"* Keelsons *"*
 Sheerstrakes *"* Clamps and Shells *"*
 Topsides *"* Ceiling *"*
 Wales *"* Rudder *"*
 Plank (Bottom) and Counter *"* Copper or Y.M. Cement When put on *75*
 Engine Room Skylights *✓* Coal Bunker, Openings, Lids, &c. *✓* Scuppers *Good* Cargo and Main Hatchways *Good* Hatches *Good*

General Observations, Opinion as to Class, &c.
Bottom sighted, cleaned and coated with paint, and the vessel being now in a good and efficient condition is eligible in my opinion to remain as Classed.

Committee's Minute *Liverpool March 19th 1878* Character assigned *100 AI.*
J. E. L. Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18

No. *-* Survey held at *Liverpool* Date, first Survey *Feb 21st* Last Survey *Feb 22nd* 1878
 in Reg. Book. on the *Ship "Merwanjee Framjee"* Master *N. P. Bidwell*
 1039 Tonnage *1079* Built at *Glasgow* When built *1863 - 5 mo.*
 By whom built *Reid* Owners *Johnston & Co.*
 Port belonging to *Liverpool* Destined Voyage *Melbourne*
 If Surveyed Afloat or in Dry Dock *Queen's Dry Dock*

Last Survey, No. *14596* Port of *Liver* Classed *S.S. Lon No 3-75.*
 Present Condition of the Decks *Good* Treanails *Rivets.* *Good*
 Waterways *"* Breasthooks and Stems *"*
 Comings *"* Transoms, Pointers, and Crutches *"*
 Upper Deck Beams & Fastenings *"* Timbers of the Frame at the Openings *"*
 Lower Deck Beams & Fastenings *"* Ditto ditto at other places *"*
 Planksheers *"* Keelsons *"*
 Sheerstrakes *"* Clamps and Shells *"*
 Topsides *"* Ceiling *"*
 Wales *"* Rudder *"*
 Plank (Bottom) and Counter *"* Copper or Y.M. Cement When put on *63*
 Engine Room Skylights *✓* Coal Bunkers, Openings, Lids, &c. *✓* Scuppers *Good* Cargo and Main Hatchways *Good* Hatches *Good*

General Observations, Opinion as to Class, &c.
Bottom sighted, cleaned and coated with paint & the vessel being now in a good and efficient condition is eligible in my opinion to remain as Classed.

Committee's Minute *Liverpool March 19th 1878* Character assigned ** AI.*
J. E. L. Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18

Mountainet
Merwanjee Shamjee

25969



© 2019

Lloyd's Register
Foundation