

20667  
**ANNUAL SURVEYS.**

No. 3978 Survey held at West Hartlepool Date, first Survey 16<sup>th</sup> March Last Survey 19<sup>th</sup> March 1878  
No. in on the Iron Steamer Wiltshire Master J Robertson  
Reg. Book. 429 Tonnage 325 Built at Hartlepool When built 1876  
By whom built Worthy Owners Steel Young & Co  
Port belonging to London Destined Voyage Malaga  
If Surveyed Afloat or in Dry Dock In Iron dry dock & afloat in

Last Survey, No. 1913 Port of Iron Classed orp 77 Years assigned. 90 A 1 Character in Register Book. 8.77  
Present Condition of the  
Decks Good  
Waterways Good  
Comings Good  
Upper Deck Beams & Fastenings Good  
Lower Deck Beams & Fastenings Good  
Planksheers Good  
Sheerstrakes Good  
Topsides Good  
Wales Good  
Plank (Bottom) and Counter Good  
Treenails Worth  
Breasthooks and Stemson Good  
Transoms, Pointers, and Crutches Good  
Timbers of the Frame at the Openings Good  
Ditto ditto at other places Good  
Keelsons Good  
Clamps and Shelves Good  
Ceiling Good  
Rudder Good  
Copper or Y.M. Good When put on Good  
Caulking of Bottom, Deck, & Waterways Good  
Windlass and Capstan Good  
Pumps Good  
Boats 3 in No  
Masts, Yards, &c. Good  
Condition, how ascertained Good  
Sails Good  
Anchors, No. of Good  
Cables Good  
Hawsers and Warps Good  
Standing and Running Rigging Good  
Engine Room Skylights Good Coal Bunker, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good  
General Observations, Opinion as to Class, &c. Now done Bottom sighted Cleaned & Painted

Is eligible in my opinion to remain as classed 90 A 1

Committee's Minute 9th April, 1878. Character assigned 90 A 1 Surveyor to Lloyd's Register of British and Foreign Shipping. Mr Davidson  
Certificate (if required) PAID 1878

No.        Survey held at        Date, first Survey        Last Survey        18        
No. in on the        Master         
Reg. Book.        Tonnage        Built at        When built         
By whom built        Owners         
Port belonging to        Destined Voyage         
If Surveyed Afloat or in Dry Dock       

Last Survey, No.        Port of        Classed        Years assigned.        Character in Register Book.         
Present Condition of the  
Decks         
Waterways         
Comings         
Upper Deck Beams & Fastenings         
Lower Deck Beams & Fastenings         
Planksheers         
Sheerstrakes         
Topsides         
Wales         
Plank (Bottom) and Counter         
Treenails         
Breasthooks and Stemson         
Transoms, Pointers, and Crutches         
Timbers of the Frame at the Openings         
Ditto ditto at other places         
Keelsons         
Clamps and Shelves         
Ceiling         
Rudder         
Copper or Y.M.        When put on         
Caulking of Bottom, Deck, & Waterways         
Windlass and Capstan         
Pumps         
Boats         
Masts, Yards, &c.         
Condition, how ascertained         
Sails         
Anchors, No. of         
Cables         
Hawsers and Warps         
Standing and Running Rigging         
Engine Room Skylights        Coal Bunkers, Openings, Lids, &c.        Scuppers        Cargo and Main Hatchways        Hatches         
General Observations, Opinion as to Class, &c.       

Committee's Minute 18 Character assigned        Surveyor to Lloyd's Register of British and Foreign Shipping.         
Certificate (if required)        Paid        18