

ANNUAL SURVEYS.

Rec'd 15.3.78

No. in Reg. Book. on the 496 No. 106 "Woolahra" Survey held at London Date, first Survey 8th March Last Survey 8th March 1878
 Master J. Barneson
 Tonnage 942 Built at Sunderland When built 1845 - 1 m^o
 By whom built W. Chaural Owners Cowlishaw Bros.
 Port belonging to Sydney Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Patetiffe Dock

Last Survey, No. 16806 Port of Lron Classed 100 A1
 Years assigned 8.76 Character in Register Book.
 Present Condition of the Vessel
 Decks Good Planks where seen Good
 Waterways d^c Breasthooks and Stemson d^c d^c
 Comings d^c Transoms, Pointers, and Crutches d^c d^c
 Upper Deck Beams & Fastenings d^c Timbers of the Frame at the Openings d^c d^c
 Lower Deck Beams & Fastenings d^c Ditto ditto at other places d^c d^c
 Planksheers d^c Keelsons d^c d^c
 Sheerstrakes d^c Clamps and Shelves d^c d^c
 Topsides d^c Ceiling d^c d^c
 Vales d^c Rudder d^c
 Copper or Y.M. ✓ When put on ✓
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights Coal Bunker, Openings, Lids, &c. Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c.

This vessel appears in good condition, where seen, and eligible to remain as classed.
Surveyed with ballast in hold

Committee's Minute 22nd March, 1878. J. P. Congdon
 Character assigned 100 A1 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) _____ Paid _____ 18

No. in Reg. Book. on the 28 No. 107 "Girvan" Survey held at London Date, first Survey 25th Feb Last Survey 12th Mar 1878
 Master Hughen
 Tonnage 694 Built at Glasgow When built 1869 - 5 mo
 By whom built Lon & Glas. Co Owners D. Hunter
 Port belonging to Ayr Destined Voyage _____
 If Surveyed Afloat or in Dry Dock In Dry Dock (Bullhead)

Last Survey, No. 18486 Port of Lron Classed A.1
 Years assigned 5.77 Character in Register Book.
 Present Condition of the Vessel
 Decks good Rivets where seen good.
 Waterways d^c Breasthooks and Stemson d^c
 Comings d^c Transoms, Pointers, and Crutches d^c
 Upper Deck Beams & Fastenings d^c Timbers of the Frame at the Openings d^c
 Lower Deck Beams & Fastenings d^c Ditto ditto at other places not seen
 Planksheers d^c Keelsons good where seen
 Sheerstrakes d^c Clamps and Shelves d^c
 Topsides d^c Ceiling d^c
 Vales d^c Rudder good
 Copper or Y.M. good When put on 1869
 Caulking of Bottom, Deck, & Waterways good
 Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers good Cargo and Main Hatchways good Hatches good
 General Observations, Opinion as to Class, &c.

This vessel appears in good condition where seen, and eligible to remain as classed.
Surveyed with Ballast in hold.

Committee's Minute 22nd March, 1878. J. P. Congdon
 Character assigned A.1 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) _____ Paid _____ 18