

# REPORT of SURVEY for REPAIRS, &c.

20690

No. 4643 Survey held at Glasgow Date, first Survey 25<sup>th</sup> March Last Survey 1<sup>st</sup> April 1878  
 Reg. Book. 226 on the S.S. "Bertha" Master Walker  
 Tonnage under Tonnage Deck 327 Built at Glasgow When built 1864 - 10  
 Ditto of Spar Deck, or Awning Deck  
 Ditto of Poop  
 Ditto of Raised Qr. Dk.  
 Ditto of Houses on Deck  
 Ditto of Forecastle  
 Gross Tonnage 398 Owners A. L. Schumann Port belonging to Glasgow  
 Crew Space, as per Rule  
 Register Tonnage, out on Beam  
 Engine Room  
 Reg. Tons as St' mer, out on Bm. 251 Residence 29, St Vincent Place Glasgow  
 By whom built Fingate Destined Voyage France  
 If Surveyed Afloat or in Dry Dock D & B Henderson & Co Ship

Length of Poop 18 ft. Ditto, Forecastle 18 ft. Ditto, Raised Quarter Deck 18 ft. Years assigned. 8 Character in Register Book. A  
 Last Survey, No. 18967 Port Trow S.S. 23.76 8.77

REPAIRS, OR EXAMINATION AS PER RULE For Damage

Two plates on flat of Bottom Starboard side renewed, and  
three other plates renewed, straightened and replated, Cement  
repaired, Bottom cleaned and painted.

## Present Condition of the

Decks <u>Good</u>	Transoms <u>Good</u>	Windlass and Capstan <u>Good</u>
Waterways <u>"</u>	Breasthooks and Stemson <u>"</u>	Pumps <u>"</u>
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>"</u>	Boats <u>3</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame at the openings <u>"</u>	Masts, Yards, &c. <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Ditto <u>"</u> at other places <u>"</u>	Condition, how ascertained <u>From deck</u>
Planksheers <u>"</u>	Keelsons <u>"</u>	Sails <u>Good</u>
Sheerstrakes <u>"</u>	Clamps and Shelves <u>"</u>	Anchors No. of <u>3 1/2 1 1/2 2 1/2</u>
Topsides <u>"</u>	Ceiling <u>"</u>	Cables <u>Good</u>
Wales <u>"</u>	Rudder <u>"</u>	Hawsers and Warps <u>and</u>
Plate <u>"</u>	Copper Cement When put on <u>ft now</u>	Standing & Running Rigging <u>Sufficient</u>
Plank (Bottom) and Counter <u>"</u>	Caulking of <u>"</u>	
Engine Room Skylights <u>Good</u>	Bottom, Deck, & Waterways <u>Good</u>	Cargo and Main Hatchways <u>Good</u>
Coal Bunker, Openings, Lids, &c. <u>Good</u>	Scuppers <u>Good</u>	Hatches <u>Good</u>

General Observations, Opinion as to Class, &c.

This vessel is now in good condition in my opinion eligible  
to remain as classed.

The Amount of Entry Fee ... £ 1 : 0 : 0 received by me, 25<sup>th</sup> April 1878

Special ... £ 2 : 2 : 0

Certificate (if required) ... £ 0 : 0 : 0

(Travelling Expenses, if any, £ 0 : 0 : 0)

Committee's Minute

30<sup>th</sup> April, 1878.

Character assigned A

Surveyor to Lloyd's Register of British and Foreign Shipping.



© 2019

Lloyd's Register  
Foundation

RON477-0292