

ANNUAL SURVEYS.

20701

Rec 20/4/78

No. 4639 Survey held at Glasgow Date, first Survey 15th March Last Survey 6th April 1878
 No. in on the Iron Ship City of Delhi Master
 Reg. Book. 1189 Tonnage 1189 Built at Glasgow When built 1867 7
 By whom built Barclay Owners C. Smith & Sons
 Port belonging to Glasgow Destined Voyage Cly
 If Surveyed Afloat or in Dry Dock Govan graving dock and afloat

Last Survey, No. 16616 Port of Iron

Classed 7AS Years assigned 7.76 Character in Register Book.

S.S. No. 2. 76

Present Condition of the Decks <u>Good</u>	Treenails <u>rotten</u> <u>good</u>	Windlass and Capstan <u>Good</u>
Waterways <u>"</u>	Breasthooks and Stenson <u>not seen</u>	Pumps <u>"</u>
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>"</u>	Boats <u>"</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame at the Openings <u>good</u>	Masts, Yards, &c. <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Ditto ditto at other places <u>"</u>	Condition, how ascertained <u>from the deck</u>
Planksheers <u>"</u>	Keelsons <u>"</u>	Sails <u>Said to be complete</u>
Sheerstrakes <u>"</u>	Clamps and Shelves <u>"</u>	Anchors, No. of <u>313 18 24</u>
Topsides <u>"</u>	Ceiling <u>"</u>	Cables <u>Said to be complete</u>
Wales <u>"</u>	Rudder <u>"</u>	Hawsers and Warps <u>"</u>
Plank (Bottom) and Counter <u>"</u>	Copper or Y.M. <u>Cum</u> When put on <u>67</u>	Standing and Running Rigging <u>"</u>
Engine Room Skylights <u>"</u>	Caulking of Bottom, Deck, & Waterways <u>Good</u>	
Coal Bunker, Openings, Lids, &c. <u>"</u>	Scuppers <u>good</u>	Cargo and Main Hatchways <u>good</u>
General Observations, Opinion as to Class, &c.		Hatches <u>good</u>

The bottom scraped and recoated. Rudder braces tightened. The mainmast increased in breadth and the tie plates reconnected. She is in good and efficient condition eligible to remain as classed 7AS

Committee's Minute 23rd April, 1878.

Character assigned 7AS

Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18

No. 4639 Survey held at Glasgow Date, first Survey 21st March Last Survey 27th March 1878
 No. in on the Iron Ship State of Virginia Master Moodie
 Reg. Book. 1584 Tonnage 3473 Built at Glasgow When built 1873 3
 By whom built Lindsay Glasgow & Co Ltd Owners The State Steam Ship Co
 Port belonging to Glasgow Destined Voyage Cly
 If Surveyed Afloat or in Dry Dock Govan graving dock

Last Survey, No. *18612 Port of Iron

Classed 100AS Years assigned 100AS Character in Register Book.

S.S. Cly No. 77 5 77

Present Condition of the Decks <u>Good</u>	Treenails <u>rotten</u> <u>good</u>	Windlass and Capstan <u>Good</u>
Waterways <u>"</u>	Breasthooks and Stenson <u>not seen</u>	Pumps <u>"</u>
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>"</u>	Boats <u>"</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame at the Openings <u>good</u>	Masts, Yards, &c. <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Ditto ditto at other places <u>"</u>	Condition, how ascertained <u>from the deck</u>
Planksheers <u>"</u>	Keelsons <u>"</u>	Sails <u>Said to be complete</u>
Sheerstrakes <u>"</u>	Clamps and Shelves <u>"</u>	Anchors, No. of <u>313 18 24</u>
Topsides <u>"</u>	Ceiling <u>"</u>	Cables <u>Said to be complete</u>
Wales <u>"</u>	Rudder <u>"</u>	Hawsers and Warps <u>good</u>
Plank (Bottom) and Counter <u>"</u>	Copper or Y.M. <u>"</u> When put on <u>"</u>	Standing and Running Rigging <u>"</u>
Engine Room Skylights <u>Good</u>	Caulking of Bottom, Deck, & Waterways <u>Good</u>	
Coal Bunkers, Openings, Lids, &c. <u>Good</u>	Scuppers <u>good</u>	Cargo and Main Hatchways <u>good</u>
General Observations, Opinion as to Class, &c.		Hatches <u>good</u>

The bottom sighted - after grounding at Greenock. She is in good and efficient condition eligible to remain as classed 100AS

Committee's Minute 23rd April, 1878.

Character assigned 100AS

Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18