

ANNUAL SURVEYS.

No. 26006

Survey held at Liverpool Date, first Survey Apr 1st Last Survey April 4th 1878.
 No. in on the Ship "East Croft" Master J. T. Pinner
 Reg. Book. 68. Tonnage 1312 Built at Belfast When built 1875-6 mo.
 By whom built Harland Owners J. Gambles.
 Port belonging to Workington Destined Voyage Melbourne
 If Surveyed Afloat or in Dry Dock Queen's Dry Dock

Last Survey, No. 16895 Port of Iron Classed 100 A1
 Years assigned. 8.76. Character in Register Book.

Present Condition of the Decks.

Waterways	Good	Treenails	Rivets.	Good	Windlass and Capstan	Good
Comings	"	Breasthooks and Stems	"	"	Pumps	"
Upper Deck Beams & Fastenings	"	Transoms, Pointers, and Crutches	"	"	Boats	"
Lower Deck Beams & Fastenings	"	Timbers of the Frame at the Openings	"	"	Masts, Yards, &c.	"
Planksheers	"	Ditto ditto at other places	"	"	Condition, how ascertained	from on board
Sheerstrakes	"	Keelsons	"	"	Sails	Good
Topsides	"	Clamps and Shells	"	"	Anchors, No. of	3B-1S-2R
Wales	"	Ceiling	"	"	Cables	part seen } Good
Plank (Bottom) and Counter	"	Rudder	"	"	Hawsers and Warps	and } Sufficient
Engine Room Skylights	✓	Copper or Y.M. Cement When put on	75	"	Standing and Running Rigging	Sufficient
Coal Bunker, Openings, Lids, &c.	✓	Caulking of Bottom, Deck, & Waterways	Good	"	Cargo and Main Hatchways	Good
Scuppers	Good	Hatches	Good	"		

General Observations, Opinion as to Class, &c.

Bottom sighted, cleaned & coated with paint, and the vessel being now in a good and efficient condition she is eligible in my opinion to remain as Classed.

Committee's Minute Liverpool April 23rd 1878

Character assigned 100 A1

T. Skilston.

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required) Paid 18

J. E. L.

No. 576 Survey held at Liverpool Date, first Survey Apr 6th Last Survey April 7th 1878.
 No. in on the Ship "Borrowdale" Master Brown
 Reg. Book. 576 Tonnage 1197 Built at Liverpool When built 1868-11 mo
 By whom built Potter. Owners J. R. Newton & Co.
 Port belonging to Liverpool. Destined Voyage Portland. Oregon.
 If Surveyed Afloat or in Dry Dock Queen's Dry Dock.

Last Survey, No. 17947 Port of Iron Classed S.S. Liv. No. 2-76.
 Years assigned. 3.77. Character in Register Book.

Present Condition of the Decks

Waterways	Good	Treenails	Rivets.	Good	Windlass and Capstan	Good
Comings	"	Breasthooks and Stems	"	"	Pumps	"
Upper Deck Beams & Fastenings	"	Transoms, Pointers, and Crutches	"	"	Boats	"
Lower Deck Beams & Fastenings	"	Timbers of the Frame at the Openings	"	"	Masts, Yards, &c.	"
Planksheers	"	Ditto ditto at other places	"	"	Condition, how ascertained	from on board
Sheerstrakes	"	Keelsons	"	"	Sails	Good
Topsides	"	Clamps and Shells	"	"	Anchors, No. of	3B-1S-2R
Wales	"	Ceiling	"	"	Cables	part seen } Good
Plank (Bottom) and Counter	"	Rudder	"	"	Hawsers and Warps	and } Sufficient
Engine Room Skylights	✓	Copper or Y.M. Cement When put on	68	"	Standing and Running Rigging	Sufficient
Coal Bunkers, Openings, Lids, &c.	✓	Caulking of Bottom, Deck, & Waterways	Good	"	Cargo and Main Hatchways	Good
Scuppers	Good	Hatches	Good	"		

General Observations, Opinion as to Class, &c.

Bottom sighted, cleaned & coated with paint, and the vessel being in a good and efficient condition, is eligible in my opinion to remain as Classed.

Committee's Minute Liverpool April 23rd 1878.

Character assigned *A1.

T. Skilston.

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required) Paid 18

J. E. L.

East Graft
Borrowdale

26000



© 2019

Lloyd's Register
Foundation