

# REPORT of SURVEY for REPAIRS, &c.

No. in Reg. Book. **No. 4062** Survey held at **Dundee** Date, first Survey **2<sup>nd</sup> June** Last Survey **2<sup>nd</sup> June** 18 **77**  
**68** on the **Iron S.S. "Harvest Queen"** Master **W. Webster**  
 Tonnage under Tonnage Deck **494** Built at **West Ayr** When built **1860 - 1**  
 Ditto of Spar Deck, or Awning Deck  
 Ditto of Poop  
 Ditto of Raised Qr. Dk.  
 Ditto of Houses on Deck  
 Ditto of Forecastle  
 Gross Tonnage **532** Owners **P.M. Duncan** Port belonging to **Dundee**  
 Crew Rule  
 Register on Beam  
 Engine  
 Register cut on Bm. **362** Residence **Office, 27 Dock Street Dundee**  
 By whom built **Pile** Destined Voyage **Coasting**  
 If Surveyed Afloat or in Dry Dock **afloat**

Length **38** ft. Ditto, Forecastle **38** ft. Ditto, Raised Quarter Deck **38** ft. Years assigned **5** Character in Register Book **A**  
 Last Survey No. **19711** Port **Iron**  
 Classed **S.S. No 3. - 64. - 5**  
**S.S. No 2. 75. - 5**

REPAIRS, OR EXAMINATION AS PER RULE

This vessel examined afloat and her main deck amidships found much worn and in a very defective condition; the transverse bulkheads requiring repair and the hold in a neglected condition as regards sealing and recoating.

Condition of the	all good excepting main deck & amidships	Treenails	Rivets where seen good	Windlass and Capstan	3 Stair Suckles	Good
Waterways	Good	Breasthooks and Stemson	"	Pumps	"	"
Decks	"	Transoms, Pointers, and Crutches	"	Boats	3 No.	"
Deck Beams & Fastenings	"	Timbers of the Frame at the openings	"	Masts, Yards, &c.	"	"
Deck Beams & Fastenings	"	Ditto Ditto at other places	✓	Condition, how ascertained	From deck	"
Sheers	"	Keelsons	"	Sails	1 Suit	Good
Trakes	"	Clamps and Shelves	"	Anchors	No. of 2 B.	"
es	"	Ceiling	"	Cables	"	"
	"	Rudder	"	Hawsers and Warps	"	"
	"	Copper	Cent. When put on 1867.	Standing & Running Rigging	"	"
(Bottom) and Counter	where seen Good	Caulking of	"	Cargo and Main Hatchways	Good	Hatches Good
Room Skylights	Good	Bottom, Deck, & Waterways	Good			
Coal Bunker, Openings, Lids, &c.	Good	Scuppers	"			

Observations, Opinion as to Class, &c.

The main deck of this vessel being defective amidships and not being convenient for the owner to renew it now, (but he will do it when fitted for new boilers next summer,) I respectfully submit that her further classification be discontinued in the meantime. See my letter 2/4<sup>th</sup> ult.

Amount of Entry Fee ... £ : : received by me, }  
 Special ... £ : : 187 }  
 Certificate (if required) ... £ : :  
 Expenses, if any, £ )

Committee's Minute 8th June, 1877.

Character assigned

Surveyor to Lloyd's Register of British and Foreign Shipping.



© 2019

Lloyd's Register Foundation

180477-0342