

REPORT of SURVEY for REPAIRS, &c.

20730

IRON 477-0346

No. 3581

No. in Reg. Book.

Survey held at Bristol

Date, first Survey 14th

Last Survey 20 March 1878

on the S.S. "J. B. Walker"

Master (Suncombe)

TONNAGE under Tonnage Deck 1435

Ditto of Spar Deck, or Awning Deck

Ditto of Poop

Ditto of Raised Qr. Dk.

Ditto of Houses on Deck

Ditto of Forecastle

Gross Tonnage 1482

Crew Space, as per Rule

Register Tonnage, cut on Beam

Engine Room

Reg. Tons as St'mer, cut on Bm. 970

Built at Middlebro'

Owners R. Exchange & Co.

Residence London

By whom built Dixon

Surveyed Afloat or in Dry Dock Albion Dry Dock

When built 1875

Port belonging to London

Destined Voyage

Official Number

Length of Poop ft.

Ditto, Forecastle ft.

Ditto, Raised Quarter Deck ft.

Last Survey, No. 18789

Port Iron

Classed 90 A. 1

6.59

REPAIRS, OR EXAMINATION AS PER RULE *in acct of Damage*

On Vessel in Dry Dock. Bottom scraped and cleaned. Stern Butts caulked and Iron Rivets renewed in forefoot. Rudder lifted. Braces and Pintles bushed. Steering gear readjusted. Thirty six lengths of upper Deck planking renewed, amidships, and on quarters with Pitch Pine, and Yellow Pine, and about 2/3 of the upper Deck caulked. Some Iron Rails and Stanchions renewed, and repaired, and other Deck fittings made good. One new life Boat, supplied, and four other boats repaired, and fitted into chocks. &c. &c.

Vessel now well coated with Paint externally.

Present Condition of the Decks	<i>Good</i>	Treenails	<i>Pine, wherever Good</i>	Windlass and Capstan	
Waterways	"	Breasthooks and Stemson	"	Pumps	<i>So far</i>
Comings	"	Transoms, Pointers, and Crutches	"	Boats	<i>as</i>
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the openings	"	Masts, Yards, &c.	<i>seen</i>
Lower Deck Beams & Fastenings	"	Ditto Ditto at other places	"	Condition, how ascertained	
Planksheers	"	Keelsons		Sails	<i>Good</i>
Sheerstrakes	"	Clamps and Shelves	<i>Stringer &c.</i>	Anchors No. of	<i>and</i>
Topsides	<i>Plating</i>	Ceiling	"	Cables	<i>Efficient</i>
Wales	"	Rudder	<i>Good</i>	Hawsers and Warps	
Plank (Bottom) and Counter	"	Copper	<i>When put on</i>	Standing & Running Rigging	
Engine Room Skylights		Caulking of			
Coal Bunker, Openings, Lids, &c.		Bottom, Deck, & Waterways	<i>Good</i>		
Scuppers					
Cargo and Main Hatchways					
Hatches					

General Observations, Opinion as to Class, &c.

The Vessel appears in good, and efficient condition, eligible to remain as classed 90 A. 1

The Amount of Entry Fee ... £ 2 : 3

Special ... £ 5

Certificate (if required) ... £

received by me

16 April 1878

Committee's Minute

18th April, 1878

Character assigned

Henry J. Syrell

Surveyor to Lloyd's Register of British and Foreign Shipping.

2019

Lloyd's Register Foundation

Mistral
3581.

J. B. Walker



© 2019

Lloyd's Register
Foundation