

ANNUAL SURVEYS.

20751

No. 12926 Survey held at So Shields Date, first Survey 7 Last Survey 8th April 1872
 No. in on the Shon S.S. "Richmond" Master J. Hawley
 Reg. Book. 1018 Tonnage 1049 Built at Middlesbrough When built 1871 10 mo
 By whom built Backhouse Owners Dixon & Harris
 Port belonging to London Destined Voyage
 If Surveyed Afloat or in Dry Dock Edward's dry dock

Last Survey, No. 1798 Port of Tross

Classed

Years assigned.

Character in Register Book.

90 A.1.

Present Condition of the Decks

Good

Timber: Rivets: Good

Waterways

do

Breasthooks and Stemson

do

Comings

do

Transoms, Pointers, and Crutches

do

Upper Deck Beams & Fastenings

do

~~Timbers of the Frames~~ at the Openings

do

Lower Deck Beams & Fastenings

do

~~Ditto~~ ditto at other places

do

Planksheers

do

Keelsons

do

Sheerstrakes

do

Clamps and Shelves

do

Topsides

do

Ceiling

do

Wales

do

Rudder

do

Plank (Bottom) and Counter

do

~~Copper or F.M.~~ When put on

Caulking of

Bottom, Deck, & Waterways

good

Windlass and Capstan

Good

Pumps

do

Boats

do

Masts, Yards, &c.

do

Condition, how ascertained as from deck

Sails

Sufficient

Anchors, No. of

do

Cables

do

Hawsers and Warps

do

Standing and Running Rigging

do

Engine Room Skylights good Coal Bunker, Openings, Lids, &c. good Scuppers good Cargo and Main Hatchways good Hatches good

General Observations, Opinion as to Class, &c.

The bottom has now been scraped and painted. She appears to be in good and efficient condition and eligible, in my opinion, to remain as classed.

Committee's Minute

26th April 1878

R. J. Reed.

Character assigned

90 A.1

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required) Paid 18

No. 12926 Survey held at So Shields Date, first Survey 7 Last Survey 16th April 1872
 No. in on the Shon S.S. "Evelyn" Master E. Fleetham
 Reg. Book. 1018 Tonnage 1230 Built at M. Hantlepool When built 1876 12 mo
 By whom built Graz Owners Grudale & Co
 Port belonging to Hantlepool Destined Voyage
 If Surveyed Afloat or in Dry Dock Edward's dry dock

Last Survey, No. 19032 Port of Tross

Classed

Years assigned.

Character in Register Book.

100 A.1.

Present Condition of the Decks

Good

Timber: Rivets: Good

Waterways

do

Breasthooks and Stemson

do

Comings

do

Transoms, Pointers, and Crutches

do

Upper Deck Beams & Fastenings

do

~~Timbers of the Frames~~ at the Openings

do

Lower Deck Beams & Fastenings

do

~~Ditto~~ ditto at other places

do

Planksheers

do

Keelsons

do

Sheerstrakes

do

Clamps and Shelves

do

Topsides

do

Ceiling

do

Wales

do

~~Copper or F.M.~~ When put on

Caulking of

Bottom, Deck, & Waterways

good

Windlass and Capstan

Good

Pumps

do

Boats

do

Masts, Yards, &c.

do

Condition, how ascertained as from deck

Sails

Sufficient

Anchors, No. of

do

Cables

do

Hawsers and Warps

do

Standing and Running Rigging

do

Engine Room Skylights good Coal Bunkers, Openings, Lids, &c. good Scuppers good Cargo and Main Hatchways good Hatches good

General Observations, Opinion as to Class, &c.

The steering gear repaired; the bottom scraped and covered with black varnish and paint. She appears to be in good and efficient condition and eligible to remain as classed.

Committee's Minute

26th April 1878

R. J. Reed.

Character assigned

100 A.1

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required) Paid 18