

ANNUAL SURVEYS.

No. 100 Survey held at London Date, first Survey 5 April 1878 Last Survey 5 April 1878
 No. in on the Sew B2 Taymouth Castle Master Fulton
 Reg. Book. 1172 Tonnage 1827 Built at Glasgow When built 1844. 3ms
 By whom built Barclay Owners D. Currie & Co
 Port belonging to London Destined Voyage
 If Surveyed Afloat or in Dry Dock Thames & Dry Dock

Last Survey, No. 19813 Port of Iron Classified 100 A L
 Years assigned. 10.44 Character in Register Book.

Present Condition of the Decks Good Good
 Waterways do Breasthooks and Stemson Good
 Comings do Transoms, Pointers, and Crutches
 Upper Deck Beams & Fastenings do Timbers of the Frame at the Openings
 Lower Deck Beams & Fastenings do Ditto ditto at other places where
 Planksheers do Keelsons
 Sheerstrakes do Clamps and Shelves
 Topsides do Ceiling seen
 Wals do Rudder Good
 Plating do Copper or Y.M. Paint When put on how
 Plank (Bottom) and Counter do Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights do Coal Bunker, Openings, Lids, &c. do Scuppers do Cargo and Main Hatchways do Hatches do

General Observations, Opinion as to Class, &c.
She is now in a good and efficient condition and is eligible in my opinion to remain as classed.

Committee's Minute 18th April, 1878 C. Pearce.
 Character assigned 100 A L Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) do Paid 18

No. 96 Survey held at London Date, first Survey 5 April 1878 Last Survey 9 April 1878
 No. in on the Sew B2 Agia Master Killcoat
 Reg. Book. 1235 Tonnage 1907 Built at Dumbarton When built 1842 - 4ms
 By whom built Denny Owners But India Stm Nav Co
 Port belonging to Glasgow Destined Voyage
 If Surveyed Afloat or in Dry Dock Thames & Dry Dock

Last Survey, No. 19675 Port of Iron Classified 100 A L
 Years assigned. 11.2.77 Character in Register Book.

Present Condition of the Decks Good Good
 Waterways do Breasthooks and Stemson Good
 Comings do Transoms, Pointers, and Crutches
 Upper Deck Beams & Fastenings do Timbers of the Frame at the Openings
 Lower Deck Beams & Fastenings do Ditto ditto at other places where
 Planksheers do Keelsons
 Sheerstrakes do Clamps and Shelves
 Topsides do Ceiling seen
 Wals do Rudder Good
 Plating do Copper or Y.M. Paint When put on how
 Plank (Bottom) and Counter do Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights do Coal Bunkers, Openings, Lids, &c. do Scuppers do Cargo and Main Hatchways do Hatches do

General Observations, Opinion as to Class, &c.
She is now in a good and efficient condition and is eligible in my opinion to remain as classed

Committee's Minute 18th April, 1878 C. Pearce.
 Character assigned 100 A L Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) do Paid 18