

# ANNUAL SURVEYS.

No. 1208065 Survey held at London Date, first Survey May 6<sup>th</sup> Last Survey May 5<sup>th</sup> 1878  
 No. in on the SS City of Aberdeen Master  
 Reg. Book. 786 Tonnage 580 Built at Glasgow When built 1873 3 M  
 By whom built Currie Owners Aberdeen S. Nav Co  
 Port belonging to Aberdeen Destined Voyage  
 If Surveyed Afloat or in Dry Dock Dry Dock

Last Survey, No. 18570 Port of Leam Classed 100A 5.77  
 Present Condition of the Decks Good Treenails Rivets Good  
 Waterways " Breasthooks and Stemson "  
 Comings " Transoms, Pointers, and Crutches "  
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "  
 Lower Deck Beams & Fastenings " Ditto ditto at other places "  
 Planksheers " Keelsons "  
 Sheerstrakes " Clamps and Shelves "  
 Topsides " Ceiling "  
 Wales " Rudder "  
 Plank (Bottom) and Counter " Copper or Y.M. Copper When put on new  
 Caulking of Bottom, Deck, & Waterways Good  
 Engine Room Skylights Good Coal Bunker, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good  
 General Observations, Opinion as to Class, &c.

*She is now in good condition & entitled to remain as classed.*

Committee's Minute 14th, May, 1878

Character assigned 100A

*Senhouse Martindale*

Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) Paid 18

No. 1208065 Survey held at London Date, first Survey May 2 Last Survey 1878  
 No. in on the BK Kingdom of Sweden Master  
 Reg. Book. 163 Tonnage 788 Built at Sunderland When built 1875 4 M  
 By whom built Morrison Owners Somman & Smith  
 Port belonging to London Destined Voyage  
 If Surveyed Afloat or in Dry Dock Dry Dock

Last Survey, No. 18303 Port of Leam Classed 100A 2.76  
 Present Condition of the Decks Good Treenails Rivets Good  
 Waterways " Breasthooks and Stemson "  
 Comings " Transoms, Pointers, and Crutches "  
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "  
 Lower Deck Beams & Fastenings " Ditto ditto at other places "  
 Planksheers " Keelsons "  
 Sheerstrakes " Clamps and Shelves "  
 Topsides " Ceiling "  
 Wales " Rudder "  
 Plank (Bottom) and Counter " Copper or Y.M. Copper When put on new  
 Caulking of Bottom, Deck, & Waterways Good  
 Engine Room Skylights " Coal Bunkers, Openings, Lids, &c. " Scuppers Good Cargo and Main Hatchways Good Hatches Good  
 General Observations, Opinion as to Class, &c.

*She is now in good condition and entitled to remain as classed.*

Committee's Minute 14th, May, 1878

Character assigned 100A

*Senhouse Martindale*

Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) Paid 18