

ANNUAL SURVEYS.

(20842) 97.179

No. 889 Survey held at London Date, first Survey April 15th Last Survey April 25 1878
 No. in on the S Lutterworth Master Mr Pearson
 Reg. Book. 889 Tonnage 883 Built at Heartlepool When built 1868 11 mo.
 By whom built Senton Owners J Gray.
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Dry Sh Ballast in

Last Survey, No. 18591 Port of Iron Classed 7A 1.577
 Present Condition of the SS M 2-77
 Decks Good Treenails Rivets Good
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder "
 Plank (Bottom) and Counter " Copper or Y.M. Coated When put on Now
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights " Coal Bunker, Openings, Lids, &c. " Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. Bottom Scraped & Coated.

She is now in good condition and entitled to remain as classed.

Senhouse Martinade

Committee's Minute 7th May 1878.

Character assigned 7A 1 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) TRW Paid 18

No. 200 Survey held at London Date, first Survey April 9 Last Survey April 27 1878
 No. in on the S Remington Master _____
 Reg. Book. 200 Tonnage 555 Built at Glasgow When built 1863 4 M
 By whom built Smith Owners C & Co
 Port belonging to Liverpool Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Dry Sh Ballast in

Last Survey, No. 18574 Port of Iron Classed 7A 1.577
 Present Condition of the SS M 2-76
 Decks Good Treenails Rivets Good
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder Pushed
 Plank (Bottom) and Counter " Copper or Y.M. Coated When put on Now
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights " Coal Bunkers, Openings, Lids, &c. " Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. Bottom Scraped & Coated.

She is now in good condition and entitled to remain as classed.

Senhouse Martinade

Committee's Minute 7th May 1878.

Character assigned 7A 1 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) TRW Paid 18