

20893
37240

REPORT of SURVEY for REPAIRS, &c.

(Reid 30.5.78)

No. 299 on the S. "Berac" Survey held at London Date, first Survey 7. May Last Survey 27 May 1878
 Reg. Book. 299 Master Lark
 Tonnage under Tonnage Deck 819 Built at Sunderland When built 1863 9th MONTH.
 Ditto of Spar Deck, or Awning Deck
 Ditto of Poop
 Ditto of Raised Qr. Dk.
 Ditto of Houses on Deck
 Owners G. D. Tyser & Co Port belonging to London
 Ditto of Forecastle
 Gross Tonnage 902 Residence
 Crew Space, as per Rule
 Register Tonnage, cut on Beam 902 By whom built Tile Destined Voyage
 Engine Room
 Reg. Tons as St' mer, cut on Bm.
 If Surveyed Afloat or in Dry Dock Bridge Dry Dock & Afloat

Length of Poop _____ ft. Ditto, Forecastle _____ ft. Ditto, Raised Quarter Deck _____ ft.
 Last Survey, No. 18561 Port Iron S.S. Lon 2-3-74 Classed A. 1. 6.44

REPAIRS, OR EXAMINATION AS PER RULE Repairs.
 This vessel has been placed in dry dock, bottom cleaned and recreated. Hold examined with Ballast therein, but where ~~found~~ ^{seen} she was found in good condition. The lower and second pintle from it have now been renewed.

Cause of Repairs to be clearly stated.


Present Condition of the Decks	<u>good</u>	Rivets <u>where seen good</u>	Windlass and Capstan	<u>good</u>
Waterways	<u>do</u>	Breasthooks and Stemson	Pumps	<u>2 do</u>
Comings	<u>do</u>	Transoms, Pointers, and Crutches	Boats	<u>5 do</u>
Upper Deck Beams & Fastenings	<u>do</u>	Timbers of the Frame at the openings	Masts, Yards, &c.	<u>do</u>
Lower Deck Beams & Fastenings	<u>do</u>	Ditto Ditto " at other places	Condition, how ascertained	<u>From Deck.</u>
Planksheers	<u>do</u>	Keelsons	Sails	<u>well found</u>
Sheerstrakes	} <u>Plating</u>	Clamps and Shelves	Anchor	No. of <u>3 B, 1 S & 2 K</u>
Topsides		Ceiling	Cables	<u>good & complete</u>
Wales		Rudder	Hawsers and Warps	<u>good & sufft.</u>
Plating (Bottom) and Counter	<u>do</u>	Cement Copper	Standing & Running Rigging	<u>good</u>
Engine Room Skylights		When put on	Cargo and Main Hatchways	<u>good</u>
Coal Bunker, Openings, Lids, &c.		<u>1863</u>	Hatches	<u>good.</u>
General Observations, Opinion as to Class, &c.		Caulking of Bottom, Deck, & Waterways	Scuppers	<u>do</u>

This vessel is now in good condition and in our opinion she is eligible to remain as classed.

J. Dodd
Wm. Coupland
 Surveyor to Lloyd's Register of British and Foreign Shipping.

The Amount of Entry Fee £ : : : received by me, }
 30/5/78 Special £ 2 : 2 : 0 } 31st May 1878
 Certificate (if required) £ - : 5 : -)

Committee's Minute _____ 31st, May. 1878
 Character assigned _____



[4,000-257771] (The Surveyors are requested not to write on or below the space for Committee's Minute.)