

ANNUAL SURVEYS.

20920 37.207

Recd 15: 5:78

No. in Reg. Book. on the 32 **No.** S Cairnbulg Survey held at London Date, first Survey April 8 Last Survey May 13 1878
 Tonnage 1567 Built at Aberdeen When built 1876 - S.M.
 By whom built Smith Owners W. Smith
 Port belonging to Aberdeen Destined Voyage _____
 If Surveyed Afloat or in Dry Dock by S.M. Ballant in

Last Survey, No. 18817 Port of Iron Classed 100A1 7-78
 Present Condition of the Decks Good Treenails Good
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder "
 Plank (Bottom) and Counter " Copper or Y.M. Copper When put on Now
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights " Coal Bunker, Openings, Lids, &c. " Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. _____

She is now in good condition and respectfully recommends her to remain as classed, the overhauler promising to place her under S.M. 1 on her return from this voyage also stating they could not do it now.

Committee's Minute 18 Senhouse Martindale
 Character assigned 100A1 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) TRW Paid 18

No. in Reg. Book. on the 468 **No.** S Rocky Hall Survey held at London Date, first Survey April 5 Last Survey May 8 1878
 Tonnage 1044 Built at Liverpool When built 1863 - S.M.
 By whom built Vernon Owners Balfour Nelhamson & Co.
 Port belonging to Liverpool Destined Voyage _____
 If Surveyed Afloat or in Dry Dock by S.M.

Last Survey, No. 17170 Port of Iron Classed A1 10-76
 Present Condition of the Decks Good Treenails Good
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder "
 Plank (Bottom) and Counter " Copper or Y.M. Copper When put on Now
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights " Coal Bunkers, Openings, Lids, &c. " Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. _____

She is now in good condition and entitled to remain as classed.

Committee's Minute 18 Senhouse Martindale
 Character assigned A1 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) TRW Paid 18