

ANNUAL SURVEYS.

No. 20958 Survey held at London Date, first Survey 6 May 1878 Last Survey 9 May 1878
 No. in on the S. Gibroy Master Leshie
 Reg. Book. 298 Tonnage 1678 Built at Glasgow When built 1875. 4 mo
 By whom built Elder Owners G. Gibroy
 Port belonging to Dundee Destined Voyage
 If Surveyed Afloat or in Dry Dock Thames Iron Works Co Dry Dock (part cargo on board)

Last Survey, No. 20212 Port of Iron Classed 100 A 1
 Present Condition of the Decks Good Treenails Rivet Good
 Waterways Good Breasthooks and Stemson Good
 Comings Good Transoms, Pointers, and Crutches Good
 Upper Deck Beams & Fastenings Good Timbers of the Frame at the Openings Good
 Lower Deck Beams & Fastenings Good Ditto ditto at other places where
 Planksheers Good Keelsons Good
 Sheerstrakes Good Clamps and Shelves Good
 Topsides Good Ceiling seen
 Wales Good Rudder Good
 Plank (Bottom) and Counter Good Copper or Y.M. Paint When put on how
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights Coal Bunker, Openings, Lids, &c. Scuppers Good Cargo and Main Hatchways Good Hatches Good

General Observations, Opinion as to Class, &c. She is now in a good and efficient condition and is eligible in my opinion to remain as classed
 Committee's Minute 21st, May. 1878.
 Character assigned 100 A 1
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18

No. 18956 Survey held at London Date, first Survey 7 May 1878 Last Survey 9 May 1878
 No. in on the S. City of Paris Master Hamilton McDonald
 Reg. Book. 858 Tonnage 990 Built at Glasgow When built 1862. 7 mo
 By whom built Cornell Owners G. Smith & Sons
 Port belonging to Glasgow Destined Voyage
 If Surveyed Afloat or in Dry Dock Victoria Dock Pontoon

Last Survey, No. 18956 Port of Iron Classed S.S. Lau No 3. 75.
 Present Condition of the Decks Good Treenails Rivets Good
 Waterways Good Breasthooks and Stemson Good
 Comings Good Transoms, Pointers, and Crutches Good
 Upper Deck Beams & Fastenings Good Timbers of the Frame at the Openings Good
 Lower Deck Beams & Fastenings Good Ditto ditto at other places where
 Planksheers Good Keelsons Good
 Sheerstrakes Good Clamps and Shelves Good
 Topsides Good Ceiling seen
 Wales Good Rudder Good
 Plank (Bottom) and Counter Good Copper or Y.M. Paint When put on how
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Good Cargo and Main Hatchways Good Hatches Good

General Observations, Opinion as to Class, &c. Surveyed with part cargo in hold. She is now in a good and efficient condition and is eligible in my opinion to remain as classed.
 Committee's Minute 21st, May. 1878.
 Character assigned 100 A 1
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18