

ANNUAL SURVEYS.

(20962)

No. 1873 Survey held at Falmouth Date, first Survey 28th May Last Survey 29th May 1878
 No. in on the Iron Barge "Gwrtheyrn Castle" Master Robert Davies
 Reg. Book. 748 Tonnage 753 Built at Sunderland When built 1876, ms.
 By whom built Osborne Owners R. Rees
 Port belonging to Carnarvon Destined Voyage Monte Video (via Cardiff)
 If Surveyed Afloat or in Dry Dock In Dry Dock

Last Survey, No. 17947 Port of Iron Classed 100A

Present Condition of the
 Decks good Treenails Rivets good Liv. 3.77
 Waterways do. Breasthooks and Stemson do.
 Comings do. Transoms, Pointers, and Crutches do.
 Upper Deck Beams & Fastenings do. Timbers of the Frames at the Openings do.
 Lower Deck Beams & Fastenings do. Ditto ditto at other places do.
 Planksheers do. Keelsons do.
 Sheerstrakes Plating do. Clamps and Shells Shingles do.
 Topsides " do. Ceiling & Battens do.
 Wales " do. Rudder do.
 Plank (Bottom) and Counter do. Copper or Y.M. Cem. When put on 1876
 Engine Room Skylights ✓ Coal Bunker, Openings, Lids, &c. ✓ Scuppers good Cargo and Main Hatchways good Hatches good
 General Observations, Opinion as to Class, &c.

This vessel has now been surveyed in Falmouth dry dock; has had her topsides & bottom cleaned and properly re-coated, with Zinc Paint; also the Cement and inner surface of the plating examined and found satisfactory: She is now in good condition, and in my opinion eligible to remain as Classed (with record 5, 78)

Committee's Minute 31st May 1878
 Character assigned 100A Surveyor to Lloyd's Register of British and Foreign Shipping.

Free Charged £1:1:0 Certificate (if required) Paid 18
 Certificate £1:5:0 in full

No. Survey held at Date, first Survey May 1878 Last Survey 18
 No. in on the Master
 Reg. Book. Tonnage Built at When built
 By whom built Owners
 Port belonging to Destined Voyage
 If Surveyed Afloat or in Dry Dock

Last Survey, No. Port of Classed

Present Condition of the
 Decks Treenails
 Waterways Breasthooks and Stemson
 Comings Transoms, Pointers, and Crutches
 Upper Deck Beams & Fastenings Timbers of the Frame at the Openings
 Lower Deck Beams & Fastenings Ditto ditto at other places
 Planksheers Keelsons
 Sheerstrakes Clamps and Shells
 Topsides Ceiling
 Wales Rudder
 Plank (Bottom) and Counter Copper or Y.M. When put on
 Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Cargo and Main Hatchways Hatches
 General Observations, Opinion as to Class, &c.

Committee's Minute 18

Character assigned Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required) Paid 18