

ANNUAL SURVEYS.

No. 22 Survey held at London Date, first Survey 7 May 1878 Last Survey 8 May 1878
 No. in on the S. Halcyon Master Crocker
 Reg. Book. 22 Tonnage 843 Built at Greenock When built 1869. 3m
 By whom built Steele Owners J. Parker & Sons
 Port belonging to Southampton Destined Voyage
 If Surveyed Afloat or in Dry Dock Green's Upper Dry Dock

Last Survey, No. 19038 Port of Iron Classed S.S. Lon No 2. 74
 Present Condition of the Decks Good Treenails Rivets Good
 Waterways Good Breasthooks and Stemson Good
 Comings Good Transoms, Pointers, and Crutches Good
 Upper Deck Beams & Fastenings Good Timbers of the Frame at the Openings Good
 Lower Deck Beams & Fastenings Good Ditto ditto at other places where
 Planksheers Good Keelsons Good
 Sheerstrakes Good Clamps and Shelves Good
 Topsides Good Ceiling seen
 Wales Good Rudder Good
 Plank (Bottom) and Counter Good Copper or Y.M. Paint When put on now
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights Coal Bunker, Openings, Lids, &c. Scuppers Good Cargo and Main Hatchways Good Hatches Good

General Observations, Opinion as to Class, &c.
She is now in a good and efficient condition and is eligible in my opinion to remain as classed.

Committee's Minute 21st May. 1878. Character assigned 100A
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18

No. 1015 Survey held at London Date, first Survey 8 May 1878 Last Survey 9 May 1878
 No. in on the S. Star of Germany Master Wilson
 Reg. Book. 1015 Tonnage 1284 Built at Belfast When built 1872. 3m
 By whom built Harland Owners J. Corry & Co.
 Port belonging to Belfast Destined Voyage
 If Surveyed Afloat or in Dry Dock Green's Lower dock

Last Survey, No. 19076 Port of Iron Classed S.S. Lon No 1. 76
 Present Condition of the Decks Good Treenails Rivets Good
 Waterways Good Breasthooks and Stemson Good
 Comings Good Transoms, Pointers, and Crutches Good
 Upper Deck Beams & Fastenings Good Timbers of the Frame at the Openings Good
 Lower Deck Beams & Fastenings Good Ditto ditto at other places where
 Planksheers Good Keelsons Good
 Sheerstrakes Good Clamps and Shelves Good
 Topsides Good Ceiling seen
 Wales Good Rudder Good
 Plank (Bottom) and Counter Good Copper or Y.M. Paint When put on now
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Good Cargo and Main Hatchways Good Hatches Good

General Observations, Opinion as to Class, &c.
She is now in a good and efficient condition and is eligible in my opinion to remain as classed.

Committee's Minute 21st May. 1878. Character assigned 100A
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18