

# ANNUAL SURVEYS.

20971  
37, 2, 03

No. in Reg. Book. on the 607 **No.** PK Juliet Survey held at London Date, first Survey \_\_\_\_\_ Last Survey May 15<sup>th</sup> 1878  
 Tonnage 1243 Built at Belfast When built 1869 1 M  
 By whom built Harland Owners C J Bowring & Co  
 Port belonging to Liverpool Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock By M Ballastin

Recd 17. 5. 78  
May 15<sup>th</sup> 1878

Last Survey, No. 18499 Port of Iron Classed 7A1 5.77  
 Present Condition of the Decks Good Treenails Rivets Good  
 Waterways " Breasthooks and Stemson "  
 Comings " Transoms, Pointers, and Crutches "  
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "  
 Lower Deck Beams & Fastenings " Ditto ditto at other places "  
 Planksheers " Keelsons "  
 Sheerstrakes " Clamps and Shelves "  
 Topsides " Ceiling "  
 Wales " Rudder "  
 Plank (Bottom) and Counter " Copper or Y.M. Copper When put on Now  
 Caulking of Bottom, Deck, & Waterways Good  
 Engine Room Skylights \_\_\_\_\_ Coal Bunker, Openings, Lids, &c. \_\_\_\_\_ Scuppers Good Cargo and Main Hatchways Good Hatches Good  
 General Observations, Opinion as to Class, &c. \_\_\_\_\_

Years assigned. 7A1 5.77  
Character in Register Book. SS No 2-77

*She is now in good condition and entitled to remain as classed.*

Committee's Minute 21<sup>st</sup> May 1878 Senhouse Martindale  
 Character assigned 7A1 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) \_\_\_\_\_ Paid \_\_\_\_\_ 18 \_\_\_\_\_  
 TBW

No. in Reg. Book. on the 318 **No.** S Isle of Erin Survey held at London Date, first Survey \_\_\_\_\_ Last Survey May 6<sup>th</sup> 1878  
 Tonnage 889 Built at Glasgow When built 1875 Y No  
 By whom built Henderson Owners S Martin  
 Port belonging to Liverpool Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock By M Ballastin

Last Survey, No. 17819 Port of Iron Classed 100A- 2.77  
 Present Condition of the Decks Good Treenails Rivets Good  
 Waterways " Breasthooks and Stemson "  
 Comings " Transoms, Pointers, and Crutches "  
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "  
 Lower Deck Beams & Fastenings " Ditto ditto at other places "  
 Planksheers " Keelsons "  
 Sheerstrakes " Clamps and Shelves "  
 Topsides " Ceiling "  
 Wales " Rudder "  
 Plank (Bottom) and Counter " Copper or Y.M. Copper When put on Now  
 Caulking of Bottom, Deck, & Waterways Good  
 Engine Room Skylights \_\_\_\_\_ Coal Bunkers, Openings, Lids, &c. \_\_\_\_\_ Scuppers Good Cargo and Main Hatchways Good Hatches Good  
 General Observations, Opinion as to Class, &c. \_\_\_\_\_

Years assigned. 100A- 2.77  
Character in Register Book. \_\_\_\_\_

*She is now in good condition and entitled to remain as classed.*

Committee's Minute 21<sup>st</sup> May 1878 Senhouse Martindale  
 Character assigned 100A1 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) \_\_\_\_\_ Paid \_\_\_\_\_ 18 \_\_\_\_\_  
 TBW

TREN 478-0103

