

ANNUAL SURVEYS.

No. 6 Survey held at London Date, first Survey and Last Survey 17 April 1878
 No. in on the Sew. In "Kaieteur" Master Teisk
 Reg. Book. 6 Tonnage 503 Built at Hartlepool When built 1876 - 11th mo
 By whom built Willy Owners Steel
 Port belonging to London Destined Voyage
 If Surveyed Afloat or in Dry Dock Bridge Dry Dock.

Last Survey, No. 18919 Port of Iron

Classed 90A.1.
 12.76

Present Condition of the

Decks <u>good</u>	<u>Keels where seen good</u>	Windlass and Capstan <u>good</u>
Waterways <u>do</u>	Breasthooks and Stemson <u>do</u>	Pumps <u>do</u>
Comings <u>do</u>	Transoms, Pointers, and Crutches <u>do</u>	Boats <u>do</u>
Upper Deck Beams & Fastenings <u>do</u>	Timbers of the Frame at the Openings <u>do</u>	Masts, Yards, &c. <u>do</u>
Lower Deck Beams & Fastenings <u>do</u>	Ditto ditto at other places <u>not seen</u>	Condition, how ascertained <u>from deck</u>
Planksheers <u>Plating</u>	Keelsons <u>where seen good</u>	Sails <u>well found</u>
Sheerstrakes <u>do</u>	Clamps and Shelves <u>do</u>	Anchors, No. of <u>3 B, 1 J, 2 K</u>
Topsides <u>do</u>	Ceiling <u>do</u>	Cables <u>complete</u>
Wales <u>do</u>	Rudder <u>do</u>	Hawsers and Warps <u>good & suff.</u>
Plank (Bottom) and Counter <u>do</u>	<u>Cement</u> <u>do</u> When put on <u>1876</u>	Standing and Running Rigging <u>do</u>
Engine Room Skylights <u>good</u>	Caulking of Bottom, Deck, & Waterways <u>good</u>	Cargo and Main Hatchways <u>good</u>
Coal Bunker, Openings, Lids, &c. <u>good</u>	Scuppers <u>do</u>	Hatches <u>good</u>

General Observations, Opinion as to Class, &c. This vessel has been placed in dry dock, bottom cleaned and repainted. Other parts of vessel examined & where seen found in good condition, and is in my opinion eligible to remain as classed.

Committee's Minute 18

Character assigned 90A.1

Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18

No. 70 Survey held at London Date, first Survey 7th May Last Survey 10th May 1878
 No. in on the Bk. "Wanlock" Master J. Tilly
 Reg. Book. 70 Tonnage 375 Built at Glasgow When built 1875 - 12th mo
 By whom built Lon & Gls Co. Owners R. Bramwell
 Port belonging to London Destined Voyage
 If Surveyed Afloat or in Dry Dock Bridge Dry Dock

Last Survey, No. 18242 Port of Scott

Classed 100A.1.
 3.77

Present Condition of the

Decks <u>good</u>	<u>Keels, where seen good</u>	Windlass and Capstan <u>good</u>
Waterways <u>do</u>	Breasthooks and Stemson <u>do</u>	Pumps <u>do</u>
Comings <u>do</u>	Transoms, Pointers, and Crutches <u>do</u>	Boats <u>do</u>
Upper Deck Beams & Fastenings <u>do</u>	Timbers of the Frame at the Openings <u>do</u>	Masts, Yards, &c. <u>do</u>
Lower Deck Beams & Fastenings <u>do</u>	Ditto ditto at other places <u>not seen</u>	Condition, how ascertained <u>from deck</u>
Planksheers <u>Plating</u>	Keelsons <u>where seen good</u>	Sails <u>well found</u>
Sheerstrakes <u>do</u>	Clamps and Shelves <u>do</u>	Anchors, No. of <u>3 B, 1 J, 2 K</u>
Topsides <u>do</u>	Ceiling <u>do</u>	Cables <u>complete</u>
Wales <u>do</u>	Rudder <u>do</u>	Hawsers and Warps <u>good & suff.</u>
Plank (Bottom) and Counter <u>do</u>	<u>Cement</u> <u>good</u> When put on <u>1875</u>	Standing and Running Rigging <u>do</u>
Engine Room Skylights <u>do</u>	Caulking of Bottom, Deck, & Waterways <u>good</u>	Cargo and Main Hatchways <u>good</u>
Coal Bunkers, Openings, Lids, &c. <u>do</u>	Scuppers <u>do</u>	Hatches <u>good</u>

General Observations, Opinion as to Class, &c. This vessel has been placed in dry dock, bottom cleaned and repainted. Hold examined with Ballast in therein, found her where seen in a good condition and eligible, in my opinion, to remain as classed.

Committee's Minute 18

Character assigned 100A.1

Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18