

ANNUAL SURVEYS.

No. ²⁶⁰⁴⁶ Survey held at Liverpool Date, first Survey May 3rd Last Survey May 6th 1878.
 No. in on the Ship "Miredale" Master W. Brown
 Reg. Book. 1219 Tonnage 1231 Built at Liverpool When built 1875 - 10 mo.
 By whom built Potter Owners J. D. Newton & Co.
 Port belonging to Liverpool Destined Voyage San Francisco.
 If Surveyed Afloat or in Dry Dock Queen's Dry Dock.

Last Survey, No. 20991 Port of Iron Classed 100 AI 3.77.
 Present Condition of the Decks Good Treanails Rivets. Good
 Waterways ✓ Breasthooks and Stems ✓
 Comings ✓ Transoms, Pointers, and Crutches ✓
 Upper Deck Beams & Fastenings ✓ Timbers of the Frame at the Openings ✓
 Lower Deck Beams & Fastenings ✓ Ditto ditto at other places ✓
 Planksheers ✓ Keelsons ✓
 Sheerstrakes ✓ Clamps and Shells ✓
 Topsides ✓ Ceiling ✓
 Wales ✓ Rudder ✓
 Plank (Bottom) and Counter ✓ Copper or Y.M. Cement When put on 75
 Engine Room Skylights ✓ Coal Bunker, Openings, Lids, &c. ✓ Caulking of Bottom, Deck, & Waterways Good
 Scuppers Good Cargo and Main Hatchways Good Hatches Good

General Observations, Opinion as to Class, &c.
Bottom sighted, cleaned and coated with paint, and the vessel being now in a good and efficient condition is eligible in my opinion to remain as Classed -

Committee's Minute Liverpool May 28th 1878 T. Shilstone.
 Character assigned 100 AI Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18

No. ✓ Survey held at Liverpool Date, first Survey Apr 30th Last Survey May 2nd 1878.
 No. in on the Ship "Pizarro" Master J. Collister.
 Reg. Book. 443 Tonnage 1358 Built at Belfast When built 1875 - 12 mo.
 By whom built Harland Owners W. J. Myers, Son & Co.
 Port belonging to Liverpool Destined Voyage Melbourne.
 If Surveyed Afloat or in Dry Dock Brunswick Dry Dock.

Last Survey, No. 17980 Port of Iron Classed 100 AI 3.77.
 Present Condition of the Decks Good Treanails Rivets. Good
 Waterways ✓ Breasthooks and Stems ✓
 Comings ✓ Transoms, Pointers, and Crutches ✓
 Upper Deck Beams & Fastenings ✓ Timbers of the Frame at the Openings ✓
 Lower Deck Beams & Fastenings ✓ Ditto ditto at other places ✓
 Planksheers ✓ Keelsons ✓
 Sheerstrakes ✓ Clamps and Shells ✓
 Topsides ✓ Ceiling ✓
 Wales ✓ Rudder ✓
 Plank (Bottom) and Counter ✓ Copper or Y.M. Cement When put on 75
 Engine Room Skylights ✓ Coal Bunkers, Openings, Lids, &c. ✓ Caulking of Bottom, Deck, & Waterways Good
 Scuppers Good Cargo and Main Hatchways Good Hatches Good

General Observations, Opinion as to Class, &c.
Bottom sighted, cleaned and coated with paint, and the vessel being now in a good & efficient condition is eligible in my opinion to remain as Classed

Committee's Minute Liverpool May 28th 1878. T. Shilstone.
 Character assigned 100 AI. Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18

Misredale

Garro

Went



© 2019

Lloyd's Register
Foundation