

Report of Survey for Repairs of Engines and Boilers.

No. 272 (Rec'd 28.5.78)
 No. in Reg. Book. 272 Survey held at London Date, first Survey _____ Last Survey May 22nd 1878
 on the S.S. Thomas Lea Master _____
 Tons 487 Owners J. Hurck Port belonging to London Classified _____ Years assigned _____ Character in Register Book A1
630

Diameter of Cylinder 36 Engines made at London YEAR _____
 Length of Stroke 28 When made 1872
 Pressure of Steam 35 By whom made Vict Docks Eng'rs Co Ltd
 Registered Horse Power 80

Particulars of Repairs and Examination Blow off & donkey suction cocks fitted to turn of bilge, Crank shaft examined, Cylinder slide examined and found good, new main boiler fitted with new mountings. The machinery of this vessel is now in good order and safe working condition.

(The Surveyors are requested not to write on this space for Commission etc.)
 (Condition of Engines and Boilers, and subsequent Repairs etc. as stated.)


The Amount of Fee ... 29/5/78 £ 4 : 0 : 0 } received by me,
 Certificate (if required) ... £ - : - : - } James J. Milton 1878

(Travelling Expenses, if any, £ _____)
 Committee's Minute _____ 31st May. 1878

James J. Milton
 Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.



It is submitted that this vessel
is eligible to have a
machinery certificate
granted and Lloyd's MC
5778 recorded


31.5.78



© 2019

Lloyd's Register
Foundation